

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SOUTH QUARTER Corner of Section 34, Township 145, Range 28, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 4/27/82 found a 3" x 5' long scribed tamarack post as set by John Curo in 1907 at lost position  
DATE
- left monument as found,  lowered monument,  removed monument (explain)
- On 5/7/82 placed a 2" x 60" galvanized iron pipe with marked brass cap.  
DATE

### SKETCH OF REFERENCE TIES

MONUMENT MARKED:


T145N R28W

SC

$\frac{1}{4}$  S34

1982

RLS 12684



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page 263909

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Dan H. Stevenson 5-14-82  
SIGNATURE DATE

Registration No. 12684

Land Surveyor,  Professional Engineer

County Surveyor  County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:55 A .M. on the 22 day of July A.D., 1982

County Recorder Dorothy Henderson

By MS, Deputy

DOCUMENT NO. 263909

Statement of Evidence:

- 1871 U.S. General Land Office survey set wood post for this corner and no bearing trees were marked for this corner as corner fell in open marsh.
- 1907 County Surveyor's Record Book B pages 323 to 327 show survey by John Curo. Curo found no evidence of the corner and reset the corner by lost method midway and on line between the SE and SW corners of Sec. 34. His distance between section corners was 5288.5'. He set a 4" by 5' long tamarack post for the corner with new bearing trees: 4" Tam N 28-15 E 53' and 3" Dead Tam, N 58-04 W 53.5'.
- 1982 After traversing between the SW and SE corners of Sec. 34 searched for the corner at lost position with USFS technician C. Krause and Cass County technician T. Freeman. We found 3" x 5' long scribed tamarack post with pointed point firmly in the ground under about 6" of water. No evidence of Curo's bearing trees were found. A 2" x 60" galvanized iron pipe with marked brass cap was set in place of post point. The scribed post was placed alongside the pipe. Four new bearing trees were scribed and are shown on this certificate. A steel sign post was set alongside the pipe and another steel sign post was set 5.0' west. We measured 5286.6' between the section corners and found the wood post to be 0.7' north and 0.5' west of the lost position. Accepted the found post as the one set by Curo by proper methods in 1907 for a lost corner.

565-60-34