CERTIFICATE OF LOCATION	OF COVERNMENT CORNER	
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTH SIXTEENTH Corner of Sections 29&30 , Township 142 , Range 30 , 5th P.M.		
STATE OF MINNESOTA, County ofCASS		
At the corner location shown on the sketch:		
On 3/12/81 found o GLO brass cap monument down 0.5' in road.		
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)		
Onplaced a		
SKETCH OF REFERENCE TIES		
1 /		
-N-		
Nail in		
8" Elm N 47 W 63.02'		
Scribe		
O , N W O T	R O A D	
Wath to		
Nail in 8" Elm	x x x	
S 56 W 154.8'	•	
£3	PASTURE	
\\X\	Nail in 6" Elm	
E3 \	S 16 W 113.6'	
	1970-BT	
ĺ	BEARINGS ARE APPROXIMATE	
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data	AGYQ30 OFFICE OF THE COUNTY RECORDER	
contained herein was prepared by me or under County of		
4	the Co. Recorders affice at 9.19 A . M. on the	
Aay H. Stevenson 9-13-82 DATE	14 day of A.D., 19 82	
Registration No. 12684	County Recorder Seulah Herdrich	
☑ Land Surveyor, □ Professional Engineer 1	By M S ,Deputy	
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 264930	

Statement of Evidence:	
1917	U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 6" Aspen S 9 E 116 links and 6" Aspen N 80 W 148 links.
1970	Corner Certificate filed by William Okerman, RLS #6807, shows GLO brass cap monument found tipped over in roadway. Found rotted Aspen stump at S 9 E 116 links. Monument was straightened and reset. Two new bearing trees marked: 5" Elm S 16 W 116.0' and 7" Elm S 56 W 155.1'. A 4"x4"x7' Cedar post was set 18.3' south.
1977	Bruce Buxton, RLS #11309, surveyed plat of FIRST ADDITION TO HEATHMAN ESTATES, filed in April 1977. The plat shows this corner in place and marked with a GLO brass cap monument.
1981	U.S. Forest Service technician W. Olson found the corner monumented with a GLO brass cap monument down 0.5' in east-west road. The following bearing trees were found: The two Elms listed in the 1970 Corner Certificate, with small discrepancy in the distances. One bearing tree was marked and is shown on this certificate.
1982	On Sept. 9 I visited the corner and found items as per the 1981 USFS reports. I accepted monument as marking the same position as when set in 1917 based on the 1970 Corner Certificate and Buxton's traverse information.