CERTIFICATE OF LOCATION OF GOVERNMENT CORNER CENTER QUARTER Corner of Section 31. Township 142 Range 30 , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On 3/12/81 found o GLO brass cap monument as set in 1917.	
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
Onplaced a	
DATE	
SKETCH OF REFERENCE TIES	
4	
No. 1 in	
Nail in 11" R. Oak N-72 W 12.66'	
Scribed :	
3	Nail in
9" R. Oak N 38 E 3.80'	
	Scribed
[3]	Nail in 7" R. Oak
tee state of the s	S 8 W 14.13' Scribed
	Scribed
BEARINGS ARE APPROXIMATE	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of
my direct supervision.	I hereby certify that this document was filed in the Co. Recorders affice at 9:00 A.M. on the
Nay D. Stevenson 9-13-82 SIGNATURE DATE	14 day of A.D., 19 82
Registration No. 12684	County Recorder Beulah Kendunka
☑ Land Surveyor, ☐ Professional Engineer	DOCUMENT NO. 264933
☐ County Surveyor, ☐ County Engineer	DOCOMENT NO A C T TV

Statement of Evidence:

- U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to markthe corner. The following bearing trees were marked: 7" R. Oak N 6½ E 62 links and 6" Poplar N 31 W 95 links.
- 1965 U.S. Forest Service records show the following: L. Witthoeft found GLO brass cap monument:
- U.S. Forest Service technician W. Olsen found the corner monumented with a GLO brass cap monument in good condition up 0.4'. The following bearing trees were found: 11" R.-Oak stump N 6½ E 40.9' rotted and mostly down. Three new bearing trees were marked and are shown on this certificate. Steel sign posts were set 4.0' west and 4.0' south of the corner.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- On Sept. 9 I visited the corner and found items as per the 1981 USFS reports. The R. Oak stump reported in 1981 is old rotted log laying to the south. I found no evidence of scribe marks. There was some evidence that an old scar faced south when the tree was standing. A 10" R. Oak appears to be growing out of the old stump. With the found monument securely in place and the evidence of the R. Oak, I accepted the monument as marking the same position as when set in 1917.