

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTH QUARTER Corner of Section 29, Township 144, Range 27, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 12/28/79 found a GLO brass cap monument as set in 1937.
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

<p>I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.</p> <p style="text-align: center;"><u>Ray H. Stevenson</u> <small>SIGNATURE</small></p> <p style="text-align: right;"><u>9-11-82</u> <small>DATE</small></p> <p>Registration No. <u>12684</u></p> <p><input checked="" type="checkbox"/> Land Surveyor, <input type="checkbox"/> Professional Engineer</p> <p><input type="checkbox"/> County Surveyor, <input type="checkbox"/> County Engineer</p>	<p style="text-align: right;"><u>264940</u></p> <p>OFFICE OF THE COUNTY RECORDER County of <u>Cass</u></p> <p>I hereby certify that this document was filed in the Co. Recorders office at <u>9:53 A.M.</u> on the <u>14</u> day of <u>Sept.</u> A.D., 19<u>82</u></p> <p>County Recorder <u>Bessie Hendrick</u> By <u>MS</u>, Deputy</p> <p>DOCUMENT NO. <u>264940</u></p>
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 4" Tamarack N 25 W 13 links and 4" Tamarack S 40 W 14 links.
- 1937 U.S. General Land Office dependent resurvey reestablished this corner by proportionate distance. No evidence was found of original corner or bearing trees. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 5" Tamarack N 44½ E 27 links and 4" Tamarack S 84½ E 85 links.
- 1979 U.S. Forest Service technician J. Schoonover found the corner monumented with a GLO brass cap monument in good condition. The following bearing trees were found: 8" Tamarack N 45 E 17.8' with scar and 6" Tamarack S 84 E 56.1' with scar. Two new bearing trees were marked and are shown on this certificate. A steel sign post was set 2.6' east of the corner.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 Analysis of the above data indicates that the location of this Government corner has been perpetuated. I accepted the monument as marking the corner location as when set in 1937 by the GLO resurvey based on bearing tree evidence.