

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 17, Township 144, Range 28, 5th P.M.

STATE OF MINNESOTA, County of CASS


At the corner location shown on the sketch:

On 1980 found original GLO bearing tree.
DATE

left monument as found, lowered monument, removed monument (explain)

On 1980 placed a 2" x 60" galvanized iron pipe with a 3" marked
DATE
brass cap.

SKETCH OF REFERENCE TIES



MONUMENT MARKED:
 T144N R28W
 $\frac{1}{4}$ $\frac{S 8}{S 17}$
 1980
 RLS No. 12684

BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Sam H. Stevenson 9-13-82
SIGNATURE DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

264941
 OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:54 A.M. on the 14 day of Sept. A.D., 1982

County Recorder Beverly Henderson
 By MS, Deputy

DOCUMENT NO. 264941

Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 6" Oak N 10 W 40 links and 4" Poplar S 65 E 65 links.
- 1980 U.S. Forest Service technician J. Schoonover found the original Oak bearing tree now a 15" W. Oak. He found the corner area by using Railroad right-of-way map information. The right-of-way map gives stationing and angle of intersection of section line with center line of railroad. No evidence was found of a corner monument or of the Poplar bearing tree. Using the record bearing and distance from the Oak, he set a 2" x 60" galvanized iron pipe with a 3" marked brass cap for the corner. The Oak was cut open and old axe blaze and negative scribe marks were found. Three new bearing trees were marked and are shown on this certificate. Steel sign posts were set 3.70' west and 4.45' east of the corner.
- 1982 On Sept. 10 I visited the corner and found items as per the 1980 USFS reports. I accepted the monument as marking the obliterated position of the original corner using the bearing tree to reestablish the original position.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.