CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 11	Township 140 , Range 25 , 5th P.M.
STATE OF MINNESOTA, County of CASS	
At the corner location shown on the sketch:	
DATE found described found of the second sec	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
✓ On <u>5-8-84</u> placed a <u>2" x 2" x 3</u> <u>DATE</u> <u>of old corner fence post.</u>	6" steel post with aluminum cap in hole
SKETCH OF REFERENCE TIES	
[ <u> </u>	
	Spike 8" Maple
-Ņ-	N 50E 83.32'
	· - · Co
Spike 8" Birch.	
N 40W 39.71	'mmm
WANG W.	
TRAIL E3	
<u> </u>	2
<i>}</i> ,	
$\beta$ ,	Spike .
کی ا	7" Twin Maple N 85E 46.29'
FIELD	N 85E 40.29
7,7	
أنحر	Fence
}	Line
·	
V.	Mamaahia Baasiana ana annuasian ta
Magnetic Bearings are approximate  Statement of evidence relative to this corner location is on back of page.	
	275705
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER  County of
my direct supervision.	
N 1 1c	I hereby certify that this document was filed in the Co. Recorders, office at 3:00 .M. on the
SIGNATURE DATE	
Registration No. 12684	County Recorder Clandine Kaylon
🕱 Land Surveyor, 🗆 Professional Engineer	By
M County Surveyor. II County Engineer	DOCUMENT NO. 275705

County Surveyor, □ County Engineer

## Statement of Evidence:

- U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 10" Aspen N 33½W 40 links, 10" Aspen S 48W 20 links, 10" Birch S 49½E 14 links, and 6" Birch N 61½E 35 links.
- County Surveyor's Record Book A pages 552 to 555 show survey by Harry S. Todd, Deputy County Surveyor. Survey notes show he found only the southwest GLO Aspen plainly marked. The other bearing trees were gone. He set a stake for the corner from the one bearing tree. Two-new bearing trees were marked: 12" Birch N 69-15E 9.85' and 14" Poplar N 18-06W 33.00'.
- Corner area was searched and no evidence was found of a corner marker or of the bearing trees. A fence line runs from the area of the East Quarter corner of Section 11 north to this corner area. And old corner fence post was found at the end of this fence that had rolled off. The distances from the East Quarter corner to the fence corner was found to be 2635 feet. This fence corner was accepted as the obliterated corner position, based on the fence corner being the best possible evidence of the original corner position. A 2" x 2" x 36" steel post with an aluminum cap was set for the corner and ties taken as shown on this certificate.