| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER | |
|---|--|
| | |
| | ,Township <u>141</u> , Range <u>28</u> , <u>5th</u> P.M. |
| STATE OF MINNESOTA, County ofCAS | <u>S</u> |
| At the corner location shown on the sketch: | |
| ☑ On 4/14/80 found a GLO brass ca | p monument as set in 1918. |
| | ed monument, 🗆 removed monument (explain) |
| | |
| Onplaced a | |
| SKETCH OF REFERENCE TIES | |
| 1 / | |
| | |
| -N- | en de la companya de La companya de la co |
| | |
| | Nail in ll" J. Pine |
| | N 76 E 100.95' Scribed |
| | ₩ Scribed |
| POND | |
| 0 | Nail in |
| | 12" J. Pine S 79 E 119.85' |
| | Scribed |
| | . ₩ - |
| | A |
| | Nail in |
| | 11" J. Pine S 55 E 140.60' |
| | Scribed |
| | BEARINGS ARE APPROXIMATE |
| Statement of evidence relative to this corner loc | |
| I hereby certify that this document and the data | OFFICE OF THE COUNTY RECORDER |
| contained herein was prepared by me or under my direct supervision. | L boroby contifue that this document was filed in |
| | I hereby certify that this document was filed in the Co. Recorders office at 3:45 .M. on the |
| Day H. Stevenon 9-15-82 SIGNATURE DATE | 10 day of <u>Dec.</u> A.D., 19 84 |
| Registration No. 12684 | County Recorder Cloudine Kaylon By MS Deputy |
| ☑ Land Surveyor, ☐ Professional Engineer | DOCUMENT NO. 279375 |
| I II COUNTY SURVEYOR II COUNTY ENGINEER | |

Statement of Evidence:

- U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 8" N. Pine S 77 E 160 links and 14" N. Pine N 60 E 170 links.
- 1918 U.S. General Land Office dependent resurvey found the corner marked by wood stake and witnessed by original bearing tree evidence:

 20" Pine stump N 52 E 170 links and 25" decayed Pine stump S 72½ E
 160 links. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: No trees available. Raised mound of stone west of the corner.
- U.S. Forest Service technician C. Krause found the corner monumented with a GLO brass cap monument in good condition 24" under water in small pond. Rock mound around corner. The following bearing trees were found: Original Pine stump N 52 E 112.2', burned and rotted, but some axe marks still visible. Four new bearing trees were marked and are shown on this certificate.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- Analysis of the above data indicates that the location of this Government corner has been perpetuated. I accepted the monument as marking the corner location as when set in 1918 by the GLO resurvey based on bearing tree evidence.