	The second secon
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
CENTER SOUTH SIXTEENTH Corner of Section 15 , Township 144 , Range 29 , 5th P.M.	
STATE OF MINNESOTA, County ofCASS	
At the corner location shown on the sketch:	
☑ On 12/30/80 found o GLO brass cap monument as set in 1926.	
UATE ,	
☑ left monument as found, □ lowered monument, □ removed monument (explain)	
Onplaced a	
OVETOU OF DEFENDANCE TIES	
SKETCH OF REFERENCE TIES	
4	
-N-	
Nail in	
10" Y. Birch S 82 W 101.61'	
Scribed .	Nail in 15" W. Oak
	S 79 E 35.0'
\(\xi_{\sum_{\color}} \)	. Scribed
	المراجعة ا
£3···:	
Nail in 8" Maple	
S 42 W 50.9' Scribed	
SCITDED	
	BEARINGS ARE APPROXIMATE
Statement of evidence relative to this corner location is on back of page.	
279377	
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER County of
my direct supervision.	I hereby certify that this document was filed in
Day A. Stevenson 9-15-82 SIGNATURE DATE	the Co. Recorders office at 2:55 P. M. on the 10 day of Dec. A.D., 1984
Registration No. 12684	County Recorder Clandine Kaylur
☑ Land Surveyor, ☐ Professional Engineer	By M.S.,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO 279377

Statement of Evidence:

- 1926 U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 8" Maple S 89 E 14 links and 8" Ironwood S 88 W 18 links.
- U.S. Forest Service records show the following: S. Morrison found the brass cap monument.
- U.S. Forest Service technician G. Brama found the corner monumented with a GLO brass cap monument in good condition up 8". The following bearing trees were found: Maple at S 88 W 11.88' with scribing. (Evidently the bearings and distances were switched between the Maple and Ironwood.) No evidence found of the Ironwood. Three new bearing trees were marked and are shown on this certificate. Steel sign posts were set 1.55' west and 1.60' north of the corner. The Maple BT was cut down.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- Analysis of the above data indicates that the location of this Government corner has been perpetuated. I accepted the monument as marking the corner location as when set in 1926 by the GLO resurvey based on bearing tree evidence.