CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER	
A.P. #1 of TR 794 Corner of Section30	Township 144, Range 30, 5th P.M.	
STATE OF MINNESOTA, County of		
At the corner location shown on the sketch:		
On 3/2/81 found a GLO brass of	cap monument as set in 1930.	
DATE		
☑ left monument as found, □ lowered monument, □ removed monument (explain)		
Onplaced a		
SKETCH OF R	EFERENCE TIES	
1		
- N-		
	Nail in	
<b> </b>	10" Ash	
	N 73 E 18.18' Scribed	
	DOLIDER	
	· · · · · · · · · · · · · · · · · · ·	
Nail in		
10" W. Oak. /		
S-84.W 14.03' Scribed		
	Nail in	
	. 18" Bur Oak S 22 E 80.13'	
	Scribed	
	€.J	
	BEARINGS ARE APPROXIMATE	
Statement of evidence relative to this corner loc	cation is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER	
contained herein was prepared by me or under	County of	
my direct supervision.	I hereby certify that this document was filed in	
Day H. Stevenson 9-15-82	the Co. Recorders office at 4:10 P. M. on the	
Registration No. 17684	County Recorder Clandine Kaylor	
Registration No100 / Professional Engineer	By MS Deputy	
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 279350	

Statement	of Evidence:
1930	U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner.
1981	U.S. Forest Service technician G. Brama found the GLO brass cap monument in good condition up 2". Three new bearing trees were marked and are shown on this certificate. Steel sign posts were set 3.5' south and 2.7' east of the corner.
1982	U.S. Forest Service technician G. Brama ran line from the Center 14 of Sec. 30 to this corner and then south to NE corner of Government Lot 10. Bearings checked good with the 1930 GLO resurvey record.
1982	Analysis of the U.S. Forest Service information indicates that the monument was found in same position as when set in 1930.
1982	County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.