

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Meander # 23 Corner of Section 32, Township 141 N, Range 31 W, 5th P.M.


STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 9/21/84 placed a 2½ inch by 5 foot galvanized pipe with 3 inch
DATE brass cap, stamped as shown, up 18 inches.

5½° East declination

SKETCH OF REFERENCE TIES not to scale



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Anthony E. Keisel 12/12/84
SIGNATURE DATE

Registration No. 12266

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

280501
OFFICE OF THE REGISTER OF DEEDS
County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 10:30 A .M. on the 25 day of February A.D., 1985

Register of Deeds Claudia Koyen
By MS County Recorder, Deputy

DOCUMENT NO. 280501

Statement of Evidence:

MEANDER CORNER No.23, SECTION 32, TOWNSHIP 141 NORTH,
RANGE 31 WEST OF THE 5th PRINCIPAL MERIDIAN. WEST SHORE
OF TENMILE LAKE.

1864 - The original Public Land Survey was run by Johnson and Thornton. Set a wood post to mark the corner and recorded two bearing trees as accessories:

8" Aspen N 60°W 17 links (11.22')

6" Willow S 50°W 25 links (16.50')

1984- Kerick Surveying, Inc., Bemidji, MN. subdivided Section 32 for the U.S. Forest Service. The only records available were the original survey. We found no trace of the original corner or its accessories. We found a 1¼" iron set by Walter Curo in 1981, did not accept this iron as the M.C. but did accept it for being on the South line of Section 32. Set a U.S.F.S. 3 inch stamped brass capped monument 16.67 feet East of Curo iron on Line single proportion between the South Quarter Corner of Section 32 and the South Quarter Corner of Section 33. New corner accessories were marked and appear on this certificate.