CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Witness Corner to between Corner of Section 5 & 8 Township 141N Range 31W , 5th P.M.	
STATE OF MINNESOTA, County ofCass	
At the corner location shown on the sketch:	
On 8-30-84 found o 2½ inch (0.D.) ieon pipe with 3 inch brass cap, stamped as shown, up 1.5 feet.	
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
Onplaced a	
Declination: 6° East NOT TO SCALE	
8 foot steel post with F.S. sign 54-9 attached, N3°E, 5.25 feet	
WC 85 8.78 S5 MC FIFTH	
8 Foot steel post with F.S. sign 54-9 attached S58°W, 5.25 feet 8 foot steel post with F.S. sign attached, S52°E, 4.95 feet	
NOTE: All steel posts are marked with F.S. sign No. 54-9.	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF COUNTY RECORDER County of I hereby certify that this document was filed in the Co. Recorder's office at 210 A .M. on the
William Of Oterma 2-1-85 SKINATURE DATE	
Registration No. 6807 B Land Surveyor, D Professional Engineer	County Recorder Cloudine Kaylon By MS Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 280554

Statement of Evidence:

Witness Corner, Meander Corner between Sections 5 & 8, Township 141 North Range 31 West, 5th Principal Meridian. West side Fifth Lake.

1873 P.H. Conger, U.S. Deputy Surveyor, set a post for this Meander Corner in his subdivision of the Township between August 5, 1873 and August 30, 1873. As references he scribed:

Willow 3 inch S79°W 12 links (7.92 feet) Willow 3 inch N81°W 12 links (7.92 feet)

- M. Stefan, R.L.S. and M. Hayes, U.S.F.S., made a thorough search for physical evidence of this corner on January 19, none was found.
- M. Hayes, U.S.F.S., returned to corner position. At the proportionate position for the lost Meander Corner, between the Meander Corner to the East and the reestablished Quarter Corner to the West, the position was found to fall in a beaver run. A Witness Corner was set which was a $2\frac{1}{2}$ inch (0.D.) x 5 foot long iron pipe with a 3 inch diameter brass cap and references as follows:

8 foot steel post N3°E 5.25 feet 8 foot steel post S58°W 5.25 feet 8 foot steel post S52°E 4.95 feet

1984 Kelly M. Booge, under F.S. Contract No. 53-6392-4-00996, made a thorough search on August 30 and found monument and ties in good condition as set by the U.S.F.S. earlier that year as shown on the sketch.

Kelly M. Booge is an employee of Okerman Surveying Inc.