CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 19 , Township 144N , Range 25W , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 10-18-1984 placed a 2 1/2" (O.D.) by 5 feet long galvinized pipe with 3" Brass Cap. Up .90 feet	
SKETCH OF REFERENCE TIES  Not to Scale  11" ASPEN  11" ASPEN  7" ASH  11" ASPEN  11" ASP	
Note:  Trees are blazed & scribed with  B.T. tags. Distances shown are to a 20 <sup>d</sup> nail in notch painted red on side of tree.	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.  3/29/85	OFFICE OF THE COUNTY RECORDER  County of
Registration No. <u>9235</u> A Land Surveyor, S Professional Engineer	By MS Deputy

DOCUMENT NO.\_\_\_\_

☐ County Surveyor, ☐ County Engineer

## Statement of Evidence:

**N5** 

This corner was originally established in April, 1876, by B.C. Baldwin, Deputy Surveyor. The field notes of that survey are filed in the office of the Secretary of State, St. Paul, Minnesota. Mr. Baldwin's notes state that a post was set to mark the corner and referenced by the following:

- A 12" Cedar that bears N60°E a distance of 12 links [7.92 feet]
- A 12" Cedar that bears S39°E a distance of 26 links [17.16 feet]
- A 12" Cedar that bears S39°W a distance of 15 links [9.90 feet]
- A 12" Cedar that bears N64'W a distance of 24 links [15.84 feet]

In 1936, Mr. Hanson, Party Chief, with the U.S. Forest Service indicates he found a scribed stake in good condition. No mention of references.

On June 11, 1984, personnel from Advance Surveying & Engineering Co. made a thorough search for this corner and the above mantioned references but to no avail.

On October 18, 1984, an additional search was made by Advance prior to reestablishing this corner by Double proportinate methods between the Northeast corner of Section 16 and the Southeast corner of Section 30 and between the Northwest corner of Section 19 and the Northeast corner of Section 20.