CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 30 , Township 144N , Ronge 25W , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
Onfound a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
M On 10-8-1984 placed a2 1/2" (O.D.) X 5 feet long galvinized iron pipe with 3" brass cap. Up 1.5 feet	
	EFERENCE TIES
5" Balsam	
\$1,1g M	G"Ash
T144N R25W N. 13 49 FT.	
519 520 530 \$29 1984 RLS 9235	
5, 6° Ash	
Note: Trees are blazed & scribed with B.T. Tags. Distances shown are to a 20 ^d nail in notch painted red on side of tree.	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER County of
James Harre 3/29/85	the Co. Recorders office at 9:55 A.M. on the 1.5 day of
Registration No. 9235	County Recorder Clanding Kaylong
Land Surveyor, A Professional Engineer County Surveyor, D County Engineer	DOCUMENT NO. 281956
i ii County Surveyor. Il County Enameer 1	

Statement of Evidence:

R5

This corner was originally established in April, 1876, by B.C. Baldwin, Deputy Surveyor. The field notes of that survey are filed in the office of the Secretary of State, St. Paul, Minnesota. Mr. Baldwin's notes state that a post was set to mark the corner and referenced by the following:

- A 8" Lynn that bears N46°E a distance of 42 links [27.72 feet]
 A 8" Ash that bears S82°E a distance of 13 links [8.58 feet]
- A 5" Ash that bears S67°W a distance of 14 links [9.24 feet]
- A 6" Ash that bears N20'W a distance of 22 links [14.52 feet]

On June 11, 1984, personnel from Advance Surveying & Engineering Co. made a thorough search for this corner and the above mentioned references but to no avail.

On October 8, 1984, an additional search was made by Advance prior to reestablishing this corner by Double proportinate methods between the Northwest corner of Section 30 and the North Quarter corner of Section 26 and between the Northeast corner of Section 7 and the Southeast corner of Section 30.