

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Center Quarter _____ Corner of Section 12, Township 141 N., Range 31 W., 5th P.M.


STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 7/13/87 found a GLO brass cap monument with top bent at 90° angle,
DATE
-broke in two when trying to straighten
- left monument as found, lowered monument, removed monument (explain)
- On 7/13/87 placed a 2" x 36" I.P. with marked brass cap.
DATE

SKETCH OF REFERENCE TIES

Not to scale



 6" Burr Oak
N 10°W 24.33'

 9" Burr Oak
 1917 GLO BT stump
 N 14°E 17.8' with
 base blaze

stump w/base blaze
 1917 GLO BT
 N 71°W 19.14'

8' FGSP NORTH 4.0' with
 LSM 30 warning sticker

CUT
 OVER
 AREA

MONUMENT STAMPED:

T141N R31W
 C1/4 S12
 1987
 RLS NO 11395

 6" Burr Oak
 S 6°E 49.53'

All BT's scribed "C1/4 S12 BT" and "BT" tags

Statement of evidence relative to this corner location is on back of page.

309686

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter E. Lemo 1-3-89
SIGNATURE DATE

Registration No. 11395

- Land Surveyor
- County Surveyor

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 3:00 P.M. on the 3 day of January A.D., 19 89

County Recorder Cloude Kayler

By MS, Deputy

DOCUMENT NO. 309686

Statement of Evidence: Center Quarter Corner Section 12,T.141 N.,R.31 W.,5th P.M.

- 1917 US General Land Office dependent resurvey established this corner by setting a 1"x36" I.P. with marked brass cap and marked the following bearing trees: 5" Jack Pine N 14°E 29 lks., 5" Jack Pine N 71°W 27 lks.
- 1984 On Nov. 28, Terry Freeman,Cass County Survey Technician and Dennis Hummitzsch,County Forester found the GLO brass cap monument in good condition and stumps of both GLO BT's. Mark two new BT's: 6" Twin Burr Oak N 7°W 25.05',4" Twin Maple N 89°W 36.48'.
- 1987 On July 13, Terry Freeman and Curt Krause, US Forest Service, found the GLO I.P. bent over at a 90° angle. 1984 ties check with the base of the iron. When trying to straighten the iron,it broke in 2 pieces. Replaced with a 2" x 36" I.P. with stamped brass cap. Both GLO BT stumps have base blaze,but no scribe visible. Mark three new BT's as shown on this certificate.