

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 35, Township 141N, Range 28W, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

On 10-19-88 found a 1918 GLO 1" x 36" iron pipe with brass cap
DATE


left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE


Monument marked

SKETCH OF REFERENCE TIES

Not to scale



Cedar 8"
 N49°W-36.96'



Tamarack 7"
 N82°E-42.83'

Sec. 26

Sign Post
 5'±

Sec. 35

Cedar 10"
 S55°W-51.94'

Cedar 6"
 S05°E-32.19'

Bearings Magnetic

All trees scribed, painted with 30d spike in side and USPS 54-3 tag

Statement of evidence relative to this corner location is on back of page.

310945

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

William C. Campbell

Date 3/17/89 Registration No. 17767

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 11:20 A. .M. on the 17 day of March A.D., 1989

County Recorder Claudia Kayler

By MS, Deputy

DOCUMENT NO. 310945

Statement of Evidence:

V-19 Quarter Corner Sections 26 & 35

- 1874 P.H. Conger set post for corner and the following references:
Tamarack 15" bears S 74 degrees W, 30 Links (19.80 feet)
Tamarack 8" bears N 60 degrees E, 33 Links (21.78 feet)
- 1918 Dependent resurvey by GLO, notes state found remains of decayed wooden stake, also found dead Tamarack 20", scribe visible, S 38 1/4 degrees W (record S 74 degrees W), 30 Links (19.80 feet) and a Tamarack 10" lying on ground, scribe visible N 61 degrees E 33 Links (21.78 feet). Added new references:
Tamarack 15" bears S 18 1/4 degrees W, 72 Links (47.52 feet)
Cedar 8" bears N 49 1/4 degrees W, 56 Links (36.96 feet)
- 1986 USFS personnel find 1918 GLO corner, also a rotted 15" Tamarack stump, S 18 degrees W, 47.52 feet. Found 9" Cedar N 49 degrees W 36.96 feet, scribe visible.
A 458 tag on Tamarack stub S 57 1/2 degrees E, 5.28 feet.
A 458 tag on Tamarack stub N 49 degrees E, 9.05 feet.
did not rebuild corner
- 5-15-88 Personnel from Landecker/Stevenson find 1918 GLO monument
Added new BT's as follows:
Tamarack 7" bears N 82 degrees E, 42.83 feet
Cedar 6" bears S 05 degrees E, 32.19 feet
Cedar 10" bears S 55 degrees W, 51.94 feet
Cedar(1918) 8" bears N 49 degrees W, 36.96 feet
- 10-19-88 Personnel from Kovanen & Osufsen Surveyors find 1918 GLO corner and all 1986 witnesses. Left monument as found and witnessed as shown on Certificate.

This position is a perpetuation of the original GLO corner.