| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER | |
|--|--|
| | |
| East Quarter Corner of Section 13 , Township 141 N, Ronge 31 W , 5th P.M. | |
| STATE OF MINNESOTA, County of | |
| At the corner location shown on the sketch: | Latitude: 47° 01' 52.655" Longitude: 94° 32' 04.294" |
| On found a DATE | |
| ☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain) | |
| ☑ On 9/20/88 placed a 2 inch by 24 inch Iron Monument with Brass Cap. | |
| Magnetic Decl: 5° East SKETCH OF R Not to Scale | EFERENCE TIES All distances are horizontal to nail in side of tree. |
| 10" Burr Oak | 7" Burr Oak N 40 E 23.09' |
| N 58 W 60.35' | |
| Overhead Powerline | Fenceline |
| FOWEITINE 40's | (|
| | 1987年,1987年,1987年,1987年 1987年 - 日本日本中の大学社 |
| Monument is located in centerline of a North-South Trail 5 feet, more or less, 8" Ma | |
| East and 40 feet, more All trees | S 13 S 18 S are painted 1988 |
| North-South. with led marked with sign post West 9 0 feet marked with sign post west 9 0 feet marked with led w | enamel and ith a 54-3 RLS No. 17008 Tree) tag. |
| Statement of evidence relative to this corner location is on back of page. 311072 | |
| I hereby certify that this survey, plan or report was prepared by me or under my | OFFICE OF THE COUNTY RECORDER County of |
| direct supervision and that ! am a duly Registered Land Surveyor under the laws | I hereby certify that this document was filed in the Co. Recorders office at 12:40 f - M. on the |
| of the State of Minnesota. | 27 day of Morel A.D., 1989 County Recorder Clarific Koylin |
| Date 3/24/89 Registration No. 17008 | DOCUMENT NO. 311072 |

Statement of Evidence:

East Quarter Corner Section 13, Township 141 North, Range 31 West, Cass County, Minnesota

> L-25 141-31 Bk.4 Pg.74

1873 P. H. Conger, U.S. Deputy Surveyor, originally established this corner position while running the east township line of Township 141 North, Range 31 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 14 inch Aspen South 72 degrees East a distance of 11 links; and an 8 inch Birch North 85 and 1/2 degrees West a distance of 5 links.

1918 U.S. General Land Office, while surveying the east line of Township 141 North, Range 31 West, did not find corner.

1988 on July 15 a Landecker-Stevenson & Associates crew searched for the corner and noted the following: that this corner position falls in centerline of North-South trail; that both original bearing tree positions fall in road; that no evidence of post or bearing trees; that a fence line runs East about 5 feet South of corner position.

1988 on September 20 a Landecker-Stevenson & Associates crew et a 2 inch by 24 inch iron pipe with brass cap and rerod in base, at the single proportional position between the northeast and southeast corners of said Section 13. 3 new bearing trees were marked as shown on front of this certificate and steel sign post is in place as shown.