

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Standard Southeast Corner of Section 31, Township 141 N, Range 29 W, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch: Latitude: 46° 58' 46.891"  
 Longitude: 94° 23' 10.827"

On \_\_\_\_\_ found a \_\_\_\_\_  
DATE



left monument as found,  lowered monument,  removed monument (explain)

On 1/28/89 placed a 2" by 48" iron pipe with brass cap, plastic  
DATE  
base and magnet.

Magnetic Decl: 5° East  
 Not to Scale

### SKETCH OF REFERENCE TIES

All distances are horizontal to nail in side of tree.



Monument is located in swamp. 8' steel sign post on West side of monument for stabilization.  
 8' steel sign post North 3.0'

Monument Stamped  
 R29  
 SC  
S31S32 T141N  
S6 T140N  
 1989  
 RLS 17008

All trees are painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

311950

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

*David S. Landecker*

David S. Landecker

Date 5-1-89 Registration No. 17008

### OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:10 A. .M. on the 9 day of May A.D., 1989

County Recorder Christine Kaye

By ms, Deputy

DOCUMENT NO. 311950

Statement of Evidence:

Standard Southeast Corner Section 31, Township  
141 North, Range 29 West, Cass County, Minnesota

Z-5 141-29  
Bk.6 Pg.21

1863 Johnson and Thornton, U.S. Deputy Surveyors, originally established this corner position while running the 10th Standard Parallel. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 6 inch Tamarack North 5 degrees West a distance of 48 links; and a 5 inch Tamarack North 73 degrees East a distance of 12 links.

1964 U.S. Forest Service records show the following: technician Ekstrom searched for corner, but found no evidence of bearing trees.

1986 U.S. Forest Service crews set an aerial target in the vicinity of this corner for the search and establishment of the true corner position. The target having coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1988 on November 10 a Landecker-Stevenson & Associates crew searched for the corner. The following information was found and noted: no evidence of original 1863 Tamarack bearing trees or post.

1989 on January 28 a Landecker-Stevenson & Associates crew set a 2 inch by 48 inch iron pipe with brass cap, plastic base and magnet at the lost, single proportion position on the 10th Standard Parallel arc between the Southwest corner of Section 31 and the Southeast corner of Section 32. New bearing trees were marked as shown and a steel sign post is in place as noted on front of this certificate.