

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Standard Southeast Corner of Section 32, Township 141 N, Range 29 W, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

Latitude: 46° 58' 46.667"
 Longitude: 94° 21' 55.003"

On _____ found a _____
DATE


left monument as found, lowered monument, removed monument (explain)

On 2/13/89 placed a 2" by 54" iron pipe with brass cap.
DATE

Magnetic Decl: 5° East
 Not to Scale

SKETCH OF REFERENCE TIES

All distances are horizontal to nail in side of tree.



5" Birch
 N 31 W 45.15'

6" Maple
 N 43 E 67.02'

24" Norway Pine
 N 69 E 130.17'

Monument is located
 250'± Westerly of
 trail and 1500' Southerly
 of Woodtick Trail.
 8' steel sign post North 5.0'
 8' steel sign post East 5.0'

Monument Stamped
 R29W
 SC
S32S33 T141N
S5 T140N
 1989
 RLS 17008

All trees are painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

311951

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 David S. Landecker

Date 5-1-89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:15 A.M. on the 9 day of May A.D., 1989

County Recorder Claudine Kayler

By ms, Deputy

DOCUMENT NO. 311951

Statement of Evidence:

Standard Southeast Corner Section 32, Township
141 North, Range 29 West, Cass County, Minnesota

Z-9 141-29
Bk.6 Pg.24

1863 Johnson and Thornton, U.S. Deputy Surveyors, originally established this corner position while running the 10th Standard Parallel. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 22 inch White Pine North 50 degrees West a distance of 12 links; and a 10 inch Linn North 52 degrees East a distance of 48 links.

1964 U.S. Forest Service records show the following: technician Ekstrom searched for corner, but found no evidence.

1974 Myron Landecker, Registered Land Surveyor Number 7452, established this corner in its lost position between the standard Southwest corner of Section 31 and Meander Corner number 1 on the East shore of Man Lake. He set a 1 inch iron pipe at this corner position. This corner is shown on the plat of ROTTIERS BABY LAKE NORTH END ADDITION.

1975 Myron Landecker, Registered Land Surveyor Number 7452, uses this corner again in the plat of HOLIDAY SHORES.

1980 Walt E. Curo, Registered Land Surveyor Number 11395, uses the 1 inch iron pipe as the corner for his survey in Government Lot 6, Section 32. This survey is of record as the plat of MOCCASIN BAY.

1986 U.S. Forest Service crews set an aerial target over this corner position for determination of coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1988 a Landecker-Stevenson & Associates crew visited the corner and found the following evidence: 2 Pine stumps easterly, no scribing or blazes visible; no evidence found of the original survey, post or accessories. Found 1 inch iron pipe as established by Myron Landecker in 1974.

1989 on February 13 a Landecker-Stevenson & Associates crew set a 2 inch by 54 inch iron pipe with brass cap, plastic base and magnet in place of 1 inch iron pipe. An evaluation of the lost position determined by this survey then found that the location as established by Myron Landecker in 1974 was acceptable. It was then determined that this position was a perpetuation of the corner using lost methods. New bearing trees were marked as shown and steel sign posts set as noted on front of this certificate.