CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East Quarter Corner of Section 10 Township 139 N., Ronge 26 W., 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On found	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 4/21/88 placed a 1 1/4" X 1 1/4" X 20" perforated steel tube with an aluminum cap, stamped "DNR SURVEY MARKER", flush.	
SKETCH OF REFERENCE TIES	
DNR nail & disc in SW side of 21" norway -N- pine, up 1.0' 263° 25.0 Possible remains of original BT-24" burnt pine stump, up 0.6' DNR nail & s	
NOTE: Azimuths observed with compass.	
15 2 7 C/1C/0B	
Statement of evidence relative to this corner location is on back of page. D.A.E. 6/16/88 File: F 761	
t hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Dollar 3-14-89	OFFICE OF THE COUNTY RECORDER County of Parallel In the Co. Recorders office at 3:40 A. M. on the 2 day of Manager Parallel In A.D. 19 A.D. 1
County Surveyor. County Engineer	DOCUMENT NO

East Quarter Corner of Section 10, Township 139 North, Range 26 West

The following offices were contacted for information concerning this corner:

MN Secretary of State Cass County Surveyor Mn/DNR Washburn Forestry Station

1863 This corner was established by the U.S. General Land Office, marked with a wood post and witnessed by:

20" Yellow Pine, N. 82° W., 24.42 feet (37 links) 20" Yellow Pine, S. 47° E., 27.72 feet (42 links)

- 1909 Book "A", page 395, records that John Curo found stubs of both bearing trees and set a 4" x 4" x 40" cedar post at the corner. He records a distance of 2628.67 feet to the section corner south.
- 1937 C.C.C. records show that they found a 3" aspen stake, 2656.50 feet south of the section corner north.
- 1952 DNR Bureau of Engineering found a 3" x 3" x 3' cedar post marking the corner. They replaced the post with an iron pin.
- The DNR Bureau of Engineering searched the area but could not find any evidence of the corner. The corner was considered lost. It was re-established midway and on line between section corners. The measured distance to the section corner south fits Curo's 1909 distance within 2 feet.

Further searching at the lost corner position revealed the remains of two stumps, burnt but solid, which fit very closely with the lost position. These stumps were considered possible bearing trees since they could not be positively identified as any markings have long since disappeared.

A DNR Survey Marker was set to perpetuate the corner position.