

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 35, Township 141 N, Range 28 W, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

Latitude: 46° 59' 33.670"
 Longitude: 94° 11' 39.756"


On 6/29/88 found a 1 inch iron monument with a brass cap (GLO)

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____

Magnetic Decl: 5⁰ East SKETCH OF REFERENCE TIES
 Not to Scale

All distances are horizontal to nail in side of tree.



Monument is located 250' more or less southerly of a highland ridge in Tamarack, Spruce, and Cedar bog. Sign post north 5.0'

Monument Stamped

$\frac{1}{4}$ S 26
S 35

1918

All trees are painted with red enamel and marked with a 54-3 (Bearing Tree) tag.

Statement of evidence relative to this corner location is on back of page.

312352

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 David S. Landecker
 Date 3/31/89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:20 A.M. on the 25 day of May A.D., 19 89

County Recorder Claudine Kugler

By ms, Deputy

DOCUMENT NO. 312352

Statement of Evidence: North Quarter Corner Section 35, Township 141
North, Range 28 West, Cass County, Minnesota

V-19 141-28
Bk.7 Pg.8

1874 P. H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 28 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 15 inch Tamarack South 74 degrees West a distance of 30 links; and an 8 inch Tamarack North 60 degrees East a distance of 33 links.

1918 U.S. General Land Office dependant resurvey found the corner marked by decayed wood stake and both original bearing trees. A 1 inch by 36 inch iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: a 15 inch Tamarack South 18 and 1/4 degrees West a distance of 72 links; and an 8 inch Cedar North 49 and 3/4 degrees West a distance of 56 links.

1986 U.S. Forest Service records show the following: find General Land Office iron and 1918 Northwest bearing tree and rotted stump of 1918 Southwest bearing tree.

1986 U.S. Forest Service crews set an aerial target over this corner position for determination of coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1988 on June 29 a Landecker-Stevenson & Associates crew visited the corner and found the following evidence: 1918 brass cap up 12 inches in good condition and the 1918 Northwest bearing tree in poor shape. New bearing trees were marked as shown and steel sign post was set as noted on front of this certificate.

1988 on October 19 personnel from Kovanen & Osufsen Surveyors find the 1918 GLO corner and all of Landecker-Stevenson witnesses. Left monument as found and witnessed as shown on certificate.

1989 on March 17 William Osufsen, Licensed Land Surveyor number 17767, files corner certificate in the office of the Cass County Recorder, as document number 310945.

1989 on April 5 David S. Landecker, Licensed Land Surveyor number 17008, prepares this corner certificate based on his corner research and 5/13/88 maintenance as noted above. He acknowledges the previous document of record filed by Osufsen for this corner and further noted the corner monument is one and the same as documented by Osufsen.