CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Standard Southeast Corner of Section 3	3 ,Township 141 N, Range 30 W , 5th P.M.
STATE OF MINNESOTA, County ofCass	
At the corner location shown on the sketch: •	Latitude: 46° 58' 48.374" Longitude: 94° 28' 13.240"
Onfound a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 4/28/89 placed a 2 inch by 24 inch iron pipe with brass cap and rerod in base, 10" below gravel road surface.	
Magnetic Decl: 5° East SKETCH OF R Not to Scale	EFERENCE TIES All distances are horizontal to nail in side of tree.
30" White Pine N 12 W 120.03'	
14" Red Oak N 42 W 81.86' 18" Red Oak N 74 E 253.46'	
Monument is located Township Road 10'± Southerly of centerline of Stoney Lake Road.	
All trees are painted with red enamental marked with a 54-3 (bearing tree)	
Statement of evidence relative to this corner location is on back of page. 3/2372	
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota. David S. Landecker	OFFICE OF THE COUNTY RECORDER County of
Date <u>5-24-89</u> Registration No. <u>17008</u>	DOCUMENT NO 3 / 2 3 7 2

Statement of Evidence:

Standard Southeast Corner Section 33, Township 141 North, Range 30 West, Cass County, Minnesota

Z-13 141-30 Bk.9 Pg.4

1863 Johnson and Thornton, U.S. Deputy Surveyors, originally established this corner position while running the 10th Standard Parallel. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 6 inch White Pine North 72 degrees West a distance of 15 links; and a 7 inch Birch North 68 degrees East a distance of 25 links.

1938 Civilian Conservation Corps found one bearing tree (not original): a 9 inch Tamarack North 40 degrees East a distance of 88 links; put location poster on it. Notes show distances along the South line of Section 33 and 34.

1964 U.S. Forest Service records show the following: technician Ekstrom searched for corner, but found no evidence.

1986 U.S. Forest Service crews set an aerial target in the vicinity of this corner for the search and establishment of the true corner position. The target having coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1988 on August 29 a Landecker-Stevenson & Associates crew searched for the corner. The following information was found and noted: point falls on south edge of East-West road; both bearing trees fall in road; 1938 location poster tree gone; no sign of Tamarack in swamp to the northeast.

1989 on March 7 a Landecker-Stevenson & Associates crew set a 2 inch by 24 inch iron pipe with brass cap and plastic base with magnet at the obliterated proportionate position along the arc of the 10th Standard Parallel using the 1938 CCC distances along the South line of Sections 33 and 34. New bearing trees were marked as shown and a steel sign post is in place as noted on front of this certificate.