

Statement of Evidence:

X13 East quarter corner section 33

1/4 Cor. 33 and 34 (E 1/4 Cor. Sec. 33)

- 1872 U.S. General Land Office survey set wood post for corner and the following references were noted:
W. Pine 6" S 87 degrees E, 26 Links (17.16 feet)
W. Pine 12" S 84 degrees W, 25 Links (16.50 feet)
- 1933 R. Emery, Book 1, Page 33, on file in Cass County Surveyors Office, lists a 1.25" iron pipe 12" above ground, he does not state if he found or set this pipe, he found a FSLP on a tree as follows:
Aspen N 25 degrees W, 12 feet
- 6-19-1940 CCC notes from Remer files, R.T. DeFant found an iron pipe which he calls a county corner, he shows fence running north, south and west from corner and adds a metal location poster to fence post at corner.
- 9-5-1968 C.Krause, USFS, found iron pipe, at corner of fences running north, south, east and west, no evidence of BT's.
- 8-7-1979 Mike Hayes, USFS, takes testimony from Mr. Don Jacobson, previous owner of the Southwest Quarter of the Southwest Quarter, he does not know the origin of this corner.
- 11-15-1989 Personnel from Kovanen & Osufsen Inc. find 1.75" O.D. iron pipe and USFS location poster on fence post 12.5 feet north, fence now runs only west, two or three post to north.
- 10-1-1990 Personnel from Kovanen & Osufsen Inc. replace iron pipe with a 2" x 48" brass capped monument, place found iron pipe along side of monument in same hole and the following witnesses:
W. Oak 6" N 37 degrees W, 53.97 feet
Ash 6" N 64 degrees W, 121.05 feet
Elm 5" N 82 degrees W, 96.72 feet
Set 8' long steel sign post with sign attached, West 4.4 feet
Set 8' long steel sign post with sign attached, North 3.1 feet

This position is not traceable to the original GLO corner, but has been accepted as corner by prior and existing owners.

Also there are records dating back to this position from 1933.