

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter _____ Corner of Section 30, Township 142, Range 31, 5th P.M.



STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 3/11/91 placed a 2 inch by 48 inch iron pipe with stamped brass
DATE
cap up 10 inches

Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
 Not to Scale

All distances are horizontal to nail in side of tree



Monument Stamped
 T142N R31W
 $\frac{1}{4}$ S.19
 $\frac{1}{4}$ S.30
 1991
 RLS 17008

Monument is located near top of knoll 70'± westerly of woods trail at west edge of cut - Aspen regeneration easterly

All trees are scribed, painted with red enamel and marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page. 3 276 06

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature] 3/26/91
SIGNATURE DATE

Registration No. 17008

- Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 4:00 P. M. on the 27 day of March A.D., 19 91

Register of Deeds Claudia Koyler
 By MJ, Deputy

DOCUMENT NO. 327606

North Quarter corner, Section 30, Township 142 North,
Range 31 West, Cass County, Minnesota

R-3 142-31

1873 P.H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 142 North, Range 31 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: an 8 inch White Pine North 35 degrees West a distance of 36 links; and an 8 inch Birch South 53 degrees East a distance of 43 links.

1990-1991 Landecker and Associates of Walker, Inc. search for corner at proportional position between Northwest and Northeast corners of Section 30 and also at a position 2640 feet west of the Northeast corner of Section 30. No evidence was found of original corner or accessories at either location. Corner was determined to be lost. On March 11, 1991 they set a 2 inch by 48 inch iron pipe with stamped brass cap at lost, single proportion position between the Northwest and Northeast corners of Section 30. New bearing trees were marked as shown and a steel sign post set as noted on front of this certificate.