CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East Quarter Corner of Section 25	8,Township140,Range27,5th P.M.
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
Onfound a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 5/7/91 placed a 2" square tubular steel monument 36" long	
with aluminum cap, up 10".	
Magnetic Decl: 5° East SKETCH OF R Not to Scale	EFERENCE TIES All distances are horizontal to nail in side of tree
N- 11" Norway Pine N 48 E 33.39'	
M.	,
Tall Names Dina	21" Norway Pine S 70 E 4.66'
11" Norway Pine S 85 W 52.84'	₩ s 70 E 4.66'
Monument is located 115't east-south of woods trail at edge of stand of	heast Monument Stamped T140N R27W 노
Jack Pine.	S28 † S27 1991
8' steel sign post with land survey monument sign 2.15' westerly.	RLS 17008
Statement of evidence relative to this corner location is on back of page. 329223	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Addition 6/10/91	OFFICE OF THE REGISTER OF DEEDS County of
☐ County Surveyor. ☐ County Engineer	DOCUMENT NO. 329 223

East Quarter corner, Section 28, Township 140 North, Range 27 West, Cass County, Minnesota

T - 13

1873 Fendall G. Winston, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 140 North, Range 27 West. The notes indicate a wood post was set and the following bearing trees were marked: a 6 inch White Pine North 46 degrees 45 minutes West a distance of 8 links; and a 10 inch Jack Pine South 50 degrees 45 minutes East a distance of 19 links.

1990 in November, a Landecker & Associates of Walker, Inc. survey crew searched for corner. On April 8, 1991, an additional corner search was made. No evidence was found at either search. On May 7, a Landecker and Associates of Walker, Inc. survey crew make final search for corner. Finding nothing, they set a 2 inch squared tubular monument 36 inches long with an aluminum cap up 10 inches at the single proportion position between the Northeast and Southeast corners of Section 28. New bearing trees were marked as shown and a steel sign post set as noted on front of this certificate.

NOTE: See subdivision map on Sheet 2 of 2 of STEVENS LAKE HOMESITES plat of record.