CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Section 27	
STATE OF MINNESOTA, County of CASS	
At the corner location shown on the sketch:	
On 7-8-91 found a BLM 5/8" COPPER ROD WITH A 1 1/2" BRONZE CAP (UP 1.0')	
DATE	
■ left monument as found, □ lowered monument, □ removed monument (explain)	
On Placed a	
SKETCH OF REFERENCE TIES	
N	
nail & DNR disc (up	o 2.0') ite aak 🤧 nail & DNR disc (up 4.0')
N 13° E 14.80°	south side 11" maple N 46° E
.n. 596	24.15
	(possible BLM 1960 tie)
nail & DNR disc (up 1.0') northeast side 8" b.aak	
N 72° W 33.76°	
(possible BLM 1960 tie)	
,/	`\
nail & DNR disc (up 0.6')	nail & DNR disc (up 2.5')
northwest side 7" b.oak S 31" W	southwest side 6" mople S 49° E
14.74' (possible BLM 1960 tie)	16.89*
(possible BLM 1900 tie)	
NOTE: ————— monument is 45° north	
of center line E-W gravel road.	gravel road
bearings observed with a compass	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of
my direct supervision.	
John D. Walker 3-26-92 SIGNATURE DATE	the Co. recorders office at $3:55$ P .M. on the
Registration No. 16098	10 day of Alexand A.D., 19 82
■ Land Surveyor, □ Professional Engineer	County Recorder Clandie Kayling
☐ County Surveyor, ☐ County Engineer	By M DOCUMENT NO. 343687

Northeast Corner Section 27, Township 140 North, Range 29 West
The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office Cass County Surveyor's Office Gary Stevenson, RLS, Walker, MN Walt Curo, RLS, Hackensack, MN Roger Mustonen, RLS, Hackensack, MN

1870 This corner was established by the U.S. General Land Office marked with a post and witnessed by the following bearing trees:

post and witnessed by the following bearing trees:

W. Pine, 20" South 20 East, 39 links (25.74')

W. Pine, 18" South 76 West, 47 links (31.02')

W. Pine, 17" North 65 West, 19 links (12.54')

Ironwood, 4" North 20 East, 32 links (21.12')

- November, Survey No. 646 containing field notes of County Surveyor, Harold Curo, indicates that he spent two days searching for remains of the original corner and its accessories. His notes state that John W. Curo spent some time in 1936 looking for the corner. Neither search resulted in any evidence of the corner. Harold Curo then set a 2" by 30" iron monument by single proportion between MC No. 41 to the west and the northeast corner of Section 26 to the east. Four ties were taken and recorded.
- 1960 August, The United States Department of Interior, Bureau of Land Management (hereinafter referred to as the BLM), represented by Hugh B. Crawford, Cadastral Surveyor, established this corner from remains of the original bearing trees. The remains of the bearing trees found:

 stump hole, North 20 Fast, 32 links

stump hole, North 20° East, 32 links stump hole, South 20° East, 39 links badly decayed white pine stump, 30", South 76° West, 47 links stump hole, North 65° West, 19 links

The BIM set a 5/8" by 36" copper rod up 1 foot with a 1-1/2" bronze cap. Four new ties were taken and recorded. The BIM further shows the distance north to MC No. 44 to be 15.94 chains (1052.04') which compares favorable with the original government distance of 16 chains (1056.00').

- 1968 June, County Surveyor, R. F. Schneider, found a 2" iron pipe in place as set by Curo in 1952. He recorded said information in Book 2 on page 3 of the field notes for Sand Lake Public Access.
- 1970 August, The plat of <u>WHITE PINE HILLS</u> as surveyed by R. F. Schneider shows an iron monument at this corner, at a distance of 925.64 feet from a monument in the vicinity of MC #44.
- June, The plat of <u>SHIRLEYJO SHORES</u> as surveyed by R. F. Schneider shows this corner to be marked with an iron pipe monument.
- August, A field crew from the Department of Natural Resources, Bureau of Engineering, found a 1-7/8" iron pipe up 0.5 of a foot. One hundred sixty feet south and forty three feet west of said iron pipe, a 5/8" copper rod with a 1-1/2" diameter bronze cap was found up 1 foot. The remains of the original southwest bearing tree could still be seen as well as all four of the BIM's 1960 tie trees.
- 1991 The copper rod with bronze cap is accepted as the section corner and ties were taken as shown on the face of this certificate.

 37kkm/Page 4