Index No.

CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
NORTHEAST Corner of Section 11 Township 134 N Range 30 W 5th P.M.	
STATE OF MINNESOTA, County of CASS	
At the corner location shown on the sketch:	
□ On 6-28-93 found a SPIKE □ DATE □ DA	
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On Placed a	
SKETCH OF REFERENCE TIES	
	!! አ
	N_ 22° W
~~~ *~~~	35.27' FOUND NAIL & DISC
2	EAST SIDE 5" OAK UP 6.0'
FOUND NAIL & DISC SW SIDE 3" OAK N 60" W	
UP 7.0' 48.84'	
xxx	· 프 · 프 · 프 ·
	C. S. A. H. 15
NOTE: MONUMENT IS	
ON CL E-W ROAD ON OLD DOWN FENCE NORTH	
ON EAST EDGE TRAIL NORTH	BEARINGS OBSERVED WITH COMPASS
Statement of evidence relative to this corner lo	cation is on back of page. SFT00039,04.00.01
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER 35/9/4
contained herein was prepared by me or under my direct supervision.	County of CASS
Locall R. Tommexerry 8-25-93	I hereby certify that this document was filed in the Co. recorders office at 4:18 PM. on the
Registration No. 17005	141hday of octuber A.D., 1993
■ Land Surveyor, ☐ Professional Engineer	By N'S Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 351914

## Northeast Corner Section 11, Township 134 North, Range 30 West

The DNR Bureau of Engineering contacted the following offices for information regarding this corner:

MN Secretary of State Cass County Surveyor Cass County Highway Engineer

- 1868 The U.S. General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and marked the following bearing trees:

  N. Pine 20" S 44 1/2° W 99 lks., N Pine 22" N 5 1/2° E 94 lks.
- No The right-of-way map for County State Aid Highway 15 shows an inplace monument at this corner. Corner is shown on the centerline of an east-west road.
- 1990 Cass County Land Corner Record Card, on file in the County Surveyor's Office, shows W. Curo set a pin and temporary ties with a county highway crew.
- June 28, the DNR Bureau of Engineering conducted a search for this corner and found a spike on the centerline of an east-west gravel road. Searched for and found the 1990 ties which agreed with the spike. Searched for but did not find any evidence of the government bearing trees. Contacted the Cass County Highway Department for further information on this corner. It was learned that a 3/4" iron rod was found at this location, but it had a bent top that would not straighten. Removed the iron rod and set a spike in its location. Spike was found to measure:

2664.38 ft. from the north quarter corner Section 11 5299.16 ft. from the northeast corner Section 14

Analysis of the available information led the DNR Bureau of Engineering to conclude that the found spike marks the location of the corner. According to the County Highway Department, the east-west road will soon be paved and they will set a monument at the spike location after paving.