

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 10, Township 134 N, Range 30 W, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

On 7-7-93 found a 1 1/4" x 24" IRON PIPE, FLUSH
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ Placed a _____
DATE

SKETCH OF REFERENCE TIES



DNR NAIL & DISC
WEST SIDE WHITE PINE
UP 1.5'




NOTE:

MONUMENT HAS
8"-10" ROCKS PILED AROUND IT AND
A 1 1/4" x 24" IRON PIPE SLOPING AWAY
FROM IT TO THE SOUTH AT A 45° ANGLE

MONUMENT IS
12.0' EAST OF CL N-S TRAIL

LOGGED



LOGGED

N 10° W
29.08'



DNR NAIL & DISC
NORTH SIDE POPLAR
UP 0.5'

TO BE
LOGGED

N 85° E
11.5'

BEARINGS OBSERVED WITH COMPASS

Statement of evidence relative to this corner location is on back of page.

SFT00039.04.00.01
J.B.M. AUG. 1993

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell R. Pomeroy Jr. 8-25-93
SIGNATURE DATE

Registration No. 17005

- Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of CASS

351915

I hereby certify that this document was filed in the Co. recorders office at 4:20 P.M. on the 14th day of OCTOBER A.D., 1993

County Recorder Claudine Kaylan
By N.B. Deputy

DOCUMENT NO. 351915

East Quarter Corner Section 10, Township 134 North, Range 30 West

The DNR Bureau of Engineering contacted the following offices for information regarding this corner:

MN Secretary of State
Cass County Surveyor
Cass County Highway Engineer

- 1868 The U.S. General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and marked the following bearing trees:
N. Pine 23" N 82° W 8 lks., N Pine 24" S 65° E 39 lks.
- 1993 July, the DNR Bureau of Engineering conducted a search for this corner and found a 1 1/4" x 24" iron pipe flush. Iron pipe has 8" - 10" rocks piled around it and another iron pipe sloping away from it at a 45° angle to the south. Searched for but did not find any ties of record, corner area has been logged off. Iron pipe was found to measure:
2650.55 ft. from the northeast corner Section 10
2651.40 ft. from the northeast corner Section 15

Analysis of the available information led the DNR Bureau of Engineering to conclude that the found iron pipe marks the location of the corner. The size and type of monument found at this corner, 1 1/4" iron pipe, is consistent with the records of other government corners in this area, per a 1911 survey.