

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTHEAST Corner of Section 14, Township 134 N, Range 30 W, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On _____ found a 3/4" INSIDE DIAMETER IRON PIPE, DOWN 0.1'
DATE _____
- left monument as found, lowered monument, removed monument (explain)
- On _____ Placed a _____
DATE _____

SKETCH OF REFERENCE TIES



NOTE:
 MONUMENT IS
 INLINE WITH CL ROAD TO EAST
 15' WEST OF CL TRAIL TO SSE
 ON WEST EDGE OF DRIVEWAY NORTH
 ON OLD DOWN FENCE TO SOUTH

BEARINGS OBSERVED WITH COMPASS

Statement of evidence relative to this corner location is on back of page.

SFT00039.04.00.01
J.B.M. AUG. 1993

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell R. Bremer 8-25-93
SIGNATURE DATE

Registration No. 17005

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER 351919
County of CASS

I hereby certify that this document was filed in the Co. recorders office at 4:28 P.M. on the 14th day of October A.D., 1993
County Recorder Claudia Kaylor
By N.S., Deputy
DOCUMENT NO. 351919

Northeast Corner Section 14, Township 134 North, Range 30 West

The DNR Bureau of Engineering contacted the following offices for information regarding this corner:

MN Secretary of State
Cass County Surveyor
Cass County Highway Engineer

- 1868 The U.S. General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and marked the following bearing trees:
N. Pine 24" S 30 1/2° W 71 lks., N. Pine 26" N 2° E 194 lks.
- 1971 Cass County Land Corner Record Card, on file in the County Surveyor's Office, shows an iron pipe at the corner by Dean Anderson. No mention is made if found or set, but four reference ties are shown to the iron pipe.
- 1982 A Sketch of a proposed road easement by Thomas Veenker, RLS#12254, shows a 1" iron pipe at this corner.
- 1985 Cass County Land Corner Record Card, on file in the County Surveyor's Office, shows a 1" iron pipe found at the corner by Freeman. Also found three reference ties from 1971. Iron pipe is in line with road centerline east and old fence south.
- 1993 June, the DNR Bureau of Engineering conducted a search for this corner and found a 3/4" inside diameter iron pipe down 0.1 ft. Searched for and found three 1971 reference ties which agree with the iron pipe, but no evidence of the government bearing trees. Iron pipe was found to measure:
2644.99 ft. from the north quarter corner Section 14
5299.16 ft. from the northeast corner Section 11
in line with centerline road east and fence line south

Analysis of the available information led the DNR Bureau of Engineering to conclude that the found iron pipe marks the location of the corner. Its position is in agreement with the local occupation in the area.