CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 23 , Township 143 , Range 25 , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
M On 10/14/94 found a 2 inch iron pipe with brass cap up 16 inches	
፟ left monument as found, □ lowered monument, □ removed monument (explain)	
□ Onplaced a	
Onplaced a	
Not to Scale 5" Black Spruce N 40 W 48.96' M4" Black S	Spruce .90' cipped out) 6" Black Spruce N 51 E 13.30' (1966 BT) MONUMENT STAMPED: T143N R25W S14 S13 S23 S24 1966
All bearing trees are scribed, painted with red enamel and marked with a 54-3 (bearing tree) tag.	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Signature BATE	OFFICE OF THE COUNTY RECORDER County of
Registration No. 21367	County Recorder Claudine Kaycan
☑ Land Surveyor	DOCUMENT NO. 365 397
· 🗆 County Surveyor	DUCUMENT NO. 365 37/

Northeast corner, Section 23, Township 143 North, Range 25 West, Cass County, Minnesota

N - 21

1872 Hayward Griffin, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 143 North, Range 25 West. The notes indicate that he set a wood post and marked the following bearing trees: a 4 inch Spruce South 11 degrees West a distance of 15 lks (9.90 feet); a 4 inch Spruce North 32 degrees East a distance of 18 lks (11.88 feet); and a 4 inch Spruce North 78 degrees West a distance of 10 lks (6.60 feet).

1966 on October 9, United States Forest Service notes in Book 1, Page 63 for Township 143 North, Range 25 West, show that Technician James Eckstrom found a very old, rotted post, rotted stump of the original Southeast bearing tree and an old C-C tag. Tie to Skunk Lake to west fits good. He set a 2 inch by 60 inch steel pipe filled with concrete and capped with bronze cap, He marked the following bearing trees: a 4 inch Black Spruce North 51 degrees East a distance of 13.30 feet; a 4 inch Black Spruce North 29 degrees West a distance of 29.90 feet; a 4 inch Black Spruce South 54 degrees West a distance of 38.70 feet; and a 4 inch Black Spruce South 53 degrees East a distance of 18.20 feet.

1976 Bureau of Land Management dependent resurvey, notes on file in Secretary of State Office, found United States Forest Service 2 and 1/2 inch iron pipe with brass cap and all 1966 bearing trees in good condition.

1979 Milo Stefan, United States Forest Service, Registered Land Surveyor Number 12261, filed "Certificate of Location of Government Corner", document #246209. Corner was set from evidence of original survey. Monument and ties are the same as the 1966 United States Forest Service report by Eckstrom.

1994 on October 14, a Landecker & Associates, Inc. survey crew traverse through corner and find 2 inch iron pipe with brass cap. On December 1, they tie out corner using 1966 bearing trees. One new bearing tree was marked as shown and steel sign posts set as noted on front of this certificate. Landecker & Associates, Inc. accepts the found monument as a perpetuation of the original corner.