

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter Corner of Section 36, Township 135 N., Range 30 W., 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On _____ found a _____
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 6-30-97 Placed a DNR survey marker, flush in the centerline
DATE of the north-south road ditch

SKETCH OF REFERENCE TIES



NAD 1983
Cass County
Coordinates
N 212,212.05
E 518,747.64

Azimuths taken with Compass

Statement of evidence relative to this corner location is on back of page.

DATE 10/21/97
FILE FOM 01856

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

John D. Walker 5/3/99
SIGNATURE DATE

License Number 16098

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER 412428
County of Cass

I hereby certify that this document was filed in the Co. recorders office at 10:30 A.M. on the 5th day of May A.D., 1999
County Recorder Claudine Taylor
By K.F., Deputy
DOCUMENT NO. 412428

East Quarter Corner Section 36, Township 135 North, Range 30 West

The Department of Natural Resources, Bureau of Engineering contacted the following offices for information regarding this corner:

MN Secretary of State
Cass County Surveyor
Cass County Highway Engineer
Central Minnesota Surveying of Brainerd
Widseth, Smith and Nolting of Brainerd
Landecker and Associates of Pequot Lakes

1858 The U.S. General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and the following bearing trees are marked:

Pine 9" S 8°E 153 links (100.98')
Aspen 12" N 30 1/2° W 173 links (114.18')

1990's Landecker and Associates used the lost position between southeast corner section 36 and the northeast corner section 25 for this corner for surveys in section 30 and 31. They did extensive traverse work in these sections and talked with local landowners before concluding the corners along this line lost. They talked with Ray Anderson and Dean Anderson, whom both come up with the same position they did.

1997 The DNR survey crew searched for evidence of this corner. Occupation was located along the section line north and south of this corner. No conclusion could be reached from the occupation lines. The crew talked to Mr. Holsapple, about 80 years old, who has lived in the area all of his life. He said the fences in section 36 don't mean much and they were just put in where the landowners thought they should go. The corner was reviewed with Landecker and Associates and Terry Freeman, the county surveyor. There are no old road records to state where the road is in relationship to the corner and the corner has been accepted as lost in previous surveys therefor the corner was accepted as lost. A DNR Survey Marker was set to mark the corner in the westerly ditch of the township road.

For more information on this corner please contact MN DNR, Bureau of Engineering, Survey Section, 500 Lafayette Road, St. Paul, MN 55155-4029.