## CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Date: 2-14-2011 License No: \_

A000568501

OFFICE OF COUNTY RECORDER CASS COUNTY MINNESOTA CERTIFIED, FILED, AND/OR RECORDED ON

02/23/2011 07:53:29 AM AS DOC #: A000568501 PAGES: 2 REC FEES: 0.00

KATHRYN M. NORBY COUNTY RECORDER

	NORTHEAST Corner of Section 31 , Township 138 , Range 30 , 5th P.M.  On 11-29-2010 found a 2"Ø IRON PIPE UP 0.8' ABOVE GROUND				
	☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)				
	Onplaced a				
$\succeq$	SVETCU OF DEFEDENCE TIES V.5				
	SKETCH OF REFERENCE TIES  Not to Scale  Corner Index: V-5				
	of the state of th				
	SET 60d NAIL IN S FACE				
141					
	\(\tilde{				
10' WIDE GRAVEL DRIVE 10.00					
	FD. 2"Ø IRON PIPE —				
	\\ \\o_{_}				
	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				
	SET 60d" NAIL IN NW FACE OF 12" POPLAR				
	ages of the same o				
	SET 60d NAIL IN NW FACE OF 8" POPLAR				
	Statement of evidence for this corner position is on the back of this page				

2 PAGES PAGE / OF\_

## **Statement of Evidence**

## Northeast corner, Section 31, Township 138 North, Range 30 West, 5<sup>th</sup> Principal Meridian, Cass County, Minnesota

1865 – Original U.S. Government Survey establishing this corner was performed. A wood post was set marking its location from which the following witnesses were established:

7" Tam.	N 4° E	144 links
8" Spruce	N 28° W	146 links
5" Tam	S 58° E	68 links

1915 – John Curo performed survey as recorded in County Book "B", pages 108-114, Survey Record 265, and in Curo book 90, page 9. No evidence was found at this corner.

1916 – Ditch Book 8, page 95 notes a measurement to this corner position but does not detail a physical corner.

1920 – Lincoln Mackey set iron monument at this corner using double proportion method as recorded in County Book "C", pages 362-363, and Survey Record No. 440.

2010 – Patrick Trottier, PLS 41002, found a 2" iron in ditch on south side of private roadway. No other local evidence found. While distances as reported by Mackey 1920 survey do not match found corners, latitude of iron fits reasonably well with section corners east and west. 2" corner accepted as perpetuation of original corner, from which the following witnesses were established:

10" Jack Pine	N 22° W	270.52 feet
12" Poplar	S 38° E	251.78 feet
8" Poplar	S 31° E	289.18 feet