

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

WC to MC #1 of Section 12, Township 143 N., Range 30 W., 5th P.M.
 State of Minnesota, County of Cass

At the corner location shown on the sketch:


On _____ found _____

- left monument as found lowered monument removed monument (explain)

On 06-16-2011 placed a 0.5" diameter rebar with a 3.5" diameter brass cap,
 flush with the surface grade.



SKETCH OF REFERENCE TIES (NOT TO SCALE)



NOTE: All bearings are true.

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed land Surveyor under the laws of the State of Minnesota. I further certify that this United States public land survey monument record is correct and complete to the best of my knowledge and belief.

Terry L. Freeman
 Terry L. Freeman, Land Surveyor

Date 2/28/12 MN License No. 21367

A000578298
OFFICE OF COUNTY RECORDER
CASS COUNTY MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON
03/01/2012 2:29:34 PM
AS DOC #: A000578298
PAGES: 2 REC FEES: 0.00
KATHRYN M. NORBY
COUNTY RECORDER

Index No. F.1 - 25.0

STATEMENT ON EVIDENCE

WC to MC #1 of Section 12, Township 143 North, Range 30 West of the 5th Principal Meridian.

In 1873, P.H. Conger, U.S. Deputy Surveyor, set a wood post in place to mark the location of this corner and established bearing trees as follows: a 6" Tamarack, N40°E 20 links and a 4" Tamarack, N11°W 20 links.

In 1924, Earl G. Harrington, U.S. Cadastral Engineer, found no evidence of the original corner and set a 1" x 36" iron pipe with stamped brass cap, raised a mound of stone alongside iron and marked a BT: a 14" Elm, N28°E 352 links. Running notes on file in Cass County Survey Department.

On June 16, 2011, a Northern Engineering & Consulting survey crew searched for corner and found nothing. They computed the lost position for the MC based on the 1924 GLO bearings from the E 1/4 through the Southeast corner of Section 1.. The position falls in the lake. They set a 1/2" rebar with a 3-1/2" diameter brass cap for a WC MC, flush with the surface grade 60.39 feet northerly of the MC position. Three ties were set as shown on the front page of this certificate.

Minnesota State Plane (Central Zone)

Northing 1137316.107
Easting 2586526.76

County Coordinates (Cass County North)

Northing 251558.222
Easting 453575.239

