

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 20, Township 143 N., Range 25 W., 5th P.M.
State of Minnesota, County of Cass

At the corner location shown on the sketch:

On 12-10-2012 found a 2-1/4" iron pipe with a 3-1/4" cap, 12" above ground level.

left monument as found lowered monument removed monument (explain)

On _____ placed _____

SKETCH OF REFERENCE TIES (NOT TO SCALE)



SE1/4-SW1/4,
SECTION 17,
T143N, R25W

SW1/4-SE1/4,
SECTION 17,
T143N, R25W

Set New Tie:
Set nail in southerly face of an
8" Tamarack, 12" above ground.



N80°W 19.73



Set New Tie:
Set nail in easterly face of a 14"
Tamarack, 12" above ground.



N29°E 26.04

Set New Tie:
Set nail in southerly face of an
8" Tamarack, 6" above ground.



N75°E 9.76

NE1/4-NW1/4,
SECTION 20,
T143N, R25W

NW1/4-NE1/4,
SECTION 20,
T143N, R25W

NOTE: All bearings are true.

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed land Surveyor under the laws of the State of Minnesota. I further certify that this united States public land survey monument record is correct and complete to the best of my knowledge and belief.

Terry L. Freeman, Land Surveyor

Date 12/28/12

MN License No. 21367



A000589929

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

2/25/2013 3:31:45 PM

AS DOC #: A000589929

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY SR _____ Dep

Page 1 of 2 A000589929



STATEMENT ON EVIDENCE

North Quarter Corner of Section 20, Township 143 North, Range 25 West of the 5th Principal Meridian.

In 1872, Hayward & Griffin, U.S. Deputy Surveyors set a wood post to mark the corner location and established bearing trees as follows: a 14" Tamarack N 77° E 25 links and a 5" Cedar S 11° E 60 links

In 1966, James Ekstrom, U.S. Forest Service personnel, searched for corner and found nothing. Information on file in the U.S.F.S. Cass Lake Office T143N R25W Book 2, page 41.

In 1976, Louis D. Gilbert, U.S. Surveyor for the BLM, made a dependent resurvey of part of the township, found nothing and set a 2½ x 28" aluminum post with stamped cap, by proportionate measurement and marked the following bearing trees: 9" Tamarack N 21° E 39.5 links and 10" Tamarack S 12° W 123 links. Information on file in the Cass County Surveyors Office.

In 2009, Laveme Leuelling, (Northern Lights Surveying & Mapping) RLS #16089, performs a survey in Section 20 and shows a found BLM monument.

On December 10, 2012, a Northern Engineering & Consulting survey crew found the 3-1/4" capped BLM monument and no existing ties. They marked 4 new ties as shown on front of this certificate. I accept the found BLM monument as set in the lost, single proportion position by the BLM and used by others.

County Coordinates (Cass County North)

Northing	242589.443
Easting	586122.168