Northeast corner Section 23, Township 139 North, Range 25 West, 5th Principal Meridian. Index No. N-21

## Statement of Evidence

Nov.16, 1863 - Johnson and Thornton, GLO Deputy Surveyors, set a post for the original corner and referenced it as follows: 3" Tam. S 20 degrees W 60 links (39.60 feet); 6" Tam. S 62  $\frac{1}{2}$  degrees E 110 links (72.60 feet); 10" Tam. N 85 degrees E 240 links (158.40 feet); 7" W. Birch N 76  $\frac{1}{2}$  degrees W 450 links (297.00 feet).

The above record is on file with the Minnesota Historical Society, St. Paul, Minnesota, copies are on file in the Cass County Surveyor's Office (CCSO).

## **CCSO Files**

May 3, 1910 - A.W.Moulster, Deputy County Surveyor, Survey Record 161, Book A, page 346, and Curo Field Book 48, page 84, states "Found 3 tamarac stumps badly rotted but checked out for measurement and courses, transit setting over an old cruisers stake. Could not find Birch N.W. I set a post by flat measures. I set new bearings as follows 8 degrees 30 min Var." 7" Tam N 82 degrees 56 min E 123.15 feet; 6" Tam S 72 degrees 52 min E 67 feet; 4" Tam S 27 degrees 43 min W 66.50 feet.

Apr. 9, 1911 J. Curo, LS 1428, Curo Field Book 74, page 8, on file in the CCSO, states "We find a 4 x 4 post set by Moulster for the true 1/4 post from old Gov't B.T.s."

1937 - Civilian Conservation Corps (CCC) personnel, Washburn Lake notes, Book 1, page 60, on file in the Minnesota Department of Natural Resources Office (MNDNR), indicate an approx corner.

1941 - CCC personnel, Washburn Lake notes, Emily Game Refuge Book, page 1, on file in the MNDNR, states that they start East from intersection of roads.

Mar.13, 2004 - B.Hippen, CCSO technician, records of the CCSO, found a 1 inch outside diameter pin, down 0.1 foot, 3 feet, more or less, east of driveway, near the centerline point of intersection of the tangents of County Road Number 58, and marked the following witnesses: 10" Tamarack N 40 degrees W 77.98 feet; 8" B. Oak S 30 degrees W 62.50 feet; 9" Tamarack N 25 degrees E 72.28 feet.

## Karvakko Engineering

Oct. 28, 2013 - Karvakko Engineering Survey Crew found a 1 inch outside diameter pin as identified by the CCSO technician and verified the witnesses as stated.

The found monument was accepted as the NE corner of Section 23.