

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Standard South Quarter Corner of Section 33
Township 145 N , Range 27 W , 5th P.M.
STATE OF MINNESOTA, COUNTY OF CASS



A000601091

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

3/20/2014 11:04:05 AM

AS DOC #: A000601091
PAGES: 2
REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER
BY SR Dep

On 06/02/2010, found a(n): 1" Iron Post with a 2.5" Brass
Cap Stamped 1937 8" Above Ground


- left monument as found
- lowered monument
- removed monument (explain)
- raised monument

On _____, set a(n): _____


See "Statement of Evidence" for further details (on back)

(reserved for recording data)

7" Tamarack Spike in
Northeast Face, Aluminum
Tag Southeast Face



4" Tamarack Spike in
South Face, Aluminum
Tag West Face



1" Iron Post with
2.5" Brass Cap
Stamped SC ¼ S33 1937
8" Above Ground



6" Tamarack Spike in
West Face, Aluminum
Tag Northwest Face

33

SC



"SKETCH OF REFERENCE TIES" (not to scale - bearings are magnetic)

Ties are measured to center of monument unless otherwise noted.

UNITS = Metric English

UTM COORDINATES, ZONE 15

Northing: 17197820.040
Easting: 1366277.319

NAD 83/1996 HARN Adjustment.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision, and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Ross Wamre
signature

6/25/13
date

Ross Wamre, Minnesota License No. 45334

Page 1 of 2 A000601091



STATEMENT OF EVIDENCE: Standard South Corner to Section 33 of Township 145 North, Range 27 West of the 5th Principal Meridian.

1871; G.R. Stuntz, for the Government Land Office established this corner and witnessed by

Tamarack 7" dia. South 35° East, 55 Links
Tamarack 6" dia. South 10° East, 67 Links

1937; GLO dependent resurvey of the Eleventh Standard Parallel North, along the South boundary of Township 145 North, through a portion of Range 26 West and through Range 27 West, 5th Principal Meridian. Hal D. Craig, found an original bearing tree and set an iron post, as determined from the original bearing tree, 3' long, 1" in dia., 28" in the ground with a brass cap marked SC ¼ S 33 1937

Dead Tamarack 10" dia. South 35° East, 55 Links marked ¼ S (1873 Tie)

New BTs:

Tamarack 4" dia. North 27 ½ ° East, 47 Links marked SC ¼ S33 BT
Tamarack 4" dia. North 46 ¾° West, 11 Links marked SC ¼ S33 BT

2010; A Kadrmaz, Lee, & Jackson survey crew found a 1' dia. Iron Post with a 2.5" brass cap marked SC ¼ S 33 1937 8" above ground, witnesses found and established as shown on the face of this certificate.

2012; Ross Wamre, RLS #45334, after analysis of record and survey information accepts this monument as the correct perpetuation of the corner.

Contacts pertaining to this corner are as follows:

Cass County Recorder's Office
Cass County Engineers Office
Cass County Surveyors Office
Northern Engineering and Consulting Inc.
United States Forest Service
MnDOT – District Office 2
Bureau of Indians Affairs – Bemidji
Bureau of Land Management's (BLM) Northeastern States Field Office