CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

OFFICE OF THE COUNTY RECORDER CASS COUNTY, MINNESOTA CERTIFIED, FILED, AND/OR Northeast Corner of Section 31 Township <u>145</u> N , Range <u>28</u> W , 5th P.M. RECORDED ON STATE OF MINNESOTA, COUNTY OF 4/24/2014 11:39:32 AM AS DOC #: A000601876 found a(n): PAGES: REC FEES: 0.00 KATHRYN M. NORBY CASS COUNTY RECORDER ☐ left monument as found ☐ lowered monument BY_SR___Dep □ removed monument (explain) ☐ raised monument □ On __03/15/2012 __, set a(n): 3.5" Aluminum Cap on 3/4"x 4" Rebar, Flush with Ground See "Statement of Evidence" for further details (on back) (reserved for recording data) NE Corner Section 30 NOTE: Tamarack Swamp T145N, R28W 5th PM 6" Tamarack with 5" Tamarack with Nail & Disk in Southwest Nail & Disk in North Face, 1' Up Face, 1' Up T-Post 3.0 T-Post T-Post **NE Corner** S 1/4 Corner N₁88'50'47" LN 88'27'03"/E Section 32 Section 30 **2623.60**' 5249.18 3.0' T145N, R28W T145N, R28W 5th PM 5th PM 3.5" Aluminum Cap on 3/4"x 4' Rebar, Flush with Ground 52 5" Tamarack with Nail & KADRMAS LEE & JACKSON 6" Tamarack with Disk in East Face, 1' Up T145N R28W Nail & Disk in 30 | 29 North Face, 1' Up 31 732 RLS No. 45334 2012- DO NOT DISTURB (STAMPED) SE Corner Section 31 T145N, R28W 5th PM "SKETCH OF REFERENCE TIES" UTM COORDINATES, ZONE 15 (not to scale — bearings are magnetic) 17203573.040 Northing: 1326229.868 Easting:_ Ties are measured to center of monument unless otherwise noted. NAD 83/1996 Adjustment. Obtained by RTK GPS observations. UNITS = ☐ Metric ☐ English I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision, and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota. signature

Ross Wamre, Minnesota License No. 45334



Page 2 of 2 A000601876

- STATEMENT OF EVIDENCE: Section Corner common to Sections 29, 30, 31 and 32 of Township 145 North, Range 28 West of the 5th Principal Meridian.
- 1873; This corner was originally established by P. H. Conger, his field notes indicate that this corner was marked by a post and witnessed by:

Tamarack 4" dia. South 48° East, 40 links Tamarack 3" dia. North 54° East, 88 links Tamarack 4" dia. North 86° West, 26 links Tamarack 3" dia. South 50° West, 90 links

- 1929; The GLO Supplemental Plat of Section 30-145-28 shows this location with bearings and distances north and west.
- 1967; James Ebstrom for the USFS, Book 1 of Township 145 North, Range 28 West, page 14, chained to this location from the Section Corner F.S. Brass Cap 19-20-29-30 and also from the approximate section corner of sections 31 and 32 from the south. Chaining both distances hit each other good according to Ebstrom. Searched 6 man hours no evidence found.
- 2010; A Kadrmas, Lee & Jackson survey crew found no evidence in a search of this corner location.
- 2012; Ross Wamre, RLS #45334, set a 3 ½" stamped Aluminum Cap on ¾" x 4' rebar, flush at a lost double proportionate measurement location. As measured from the Northeast corner and South Quarter Corner of Section 30-145-28 the Northeast Corner of Section 32-145-28, & the Southeast Corner of Section 31-145-28. Witness found and established as shown on the front of this certificate.

Contacts pertaining to this corner are as follows:
Cass County Recorder's Office
Cass County Engineers Office
Cass County Surveyors Office
Northern Engineering and Consulting Inc.
United States Forest Service
MnDOT – District Office 2
Bureau of Indians Affairs – Bemidji
Bureau of Land Management's (BLM) Northeastern States Field Office