



A000636644

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

11/30/2017 11:06:24 AM

AS DOC #: A000636644

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY SR _____ Dep TX#: 142984

Page 1 of 2
A000636644

Index No. Q.2-5.0

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Meander corner between Sections 19 and 20, Township 142 N., Range 30 W., 5th P.M.
State of Minnesota, County of Cass.

At the corner location shown on the sketch:



On _____ found _____

- left monument as found
- lowered monument
- removed monument (explain)

On September 21, 2017 placed a 1/2 inch by 36 inch capped pipe 7± south of shoreline.

SKETCH OF REFERENCE TIES NOT TO SCALE

SET 1/2" X 36" IRON PIPE
WITH YELLOW PLASTIC CAP
STAMPED AS FOLLOWS:



NOTE:
All bearings are true

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Randy M. Morton, Licensed Land Surveyor
Date: 9/21/17 Minnesota License No. 21401

Statement of Evidence**MC between Sections 19 and 20, Township 142 North, Range 30 West, 5th P.M.****September 1873**

P.H. Conger, General Land Office (GLO) Deputy Surveyor, in the notes of the subdivision of Township 142 North, Range 30 West, set a post for the meander corner between Sections 19 and 20 and established a bearing tree as follows:

6" White Pine S20°W 17 links 11.22 feet

September 1912

Fred Demmitt, US Surveyor General, prepared a Supplemental Plat of Sections 9, 10, 15, 17, 18, 19 and 20, Township 142 North, Range 20 West, for the Leech Lake Indian Reservation re-numbering the Government Lots for the above listed sections.

August 1917

Albinus N. Kimmell, US Cadastral Engineer, surveyed and prepared a Resurvey Plat of a portion of Township 142 North, Range 30 West, within the Leech Lake Indian Reservation, approved by the Department of Interior, General Land Office December 17, 1923. Notes indicate he was unable to find the original MC and he set a 1" by 36" iron pipe with stamped brass cap and raised mound of stone west of the corner. Resurvey Plat and notes shows Meander Corner position 15.80 chains (1042.8 feet) north from the southeast corner of Section 19.

December 1965

Survey by R. F. Schneider shows subdividing part of the Southwest Quarter of Section 20, Township 142 North, Range 30 West, and shows iron pipe monuments set on the south and west lines of the Southeast Quarter of the Southwest Quarter.

January 2007

Certificate of Survey by Terry Freeman, Landecker & Associates, Inc. shows subdividing part of the South Half of the Northwest Quarter of the Southeast Quarter of Section 19, Township 142 North, Range 30 West, and shows two found GLO monuments along the south line of the South Half of the Northwest Quarter of the Southeast Quarter of Section 19.

November 2007

Certificate of Survey by Corey J. Hendershott, Landecker & Associates, Inc. shows subdividing part of the Southeast Quarter of the Southwest Quarter of Section 20, Township 142 North, Range 30 West, and shows found GLO monuments and set iron monuments on the south and west lines of the Southeast Quarter of the Southwest Quarter.

October 2010

Certificate of Survey by Terry Freeman, Northern Engineering & Consulting, Inc. shows subdividing the Southeast Quarter of Section 19, Township 142 North, Range 30 West, and shows several found GLO monuments within the Southeast Quarter of Section 19.

September 2017

Certificate of Survey by Randy M. Morton, JPJ Engineering, Inc., under contract with the U. S. Forest Service surveying parcels within the Southeast Quarter of Section 19 and the Southwest Quarter of Section 20, Township 142 North, Range 30 West, to establish the Meander Corner position between Section 19 and Section 20 near the south shoreline of Leech Lake. JPJ Engineering, Inc. Survey Crew Chief, Dustin Schmaltz, searched for the meander corner and evidence of the corner and bearing tree noted above in the original survey. No evidence was found, therefore we set a 1/2" by 36" iron pipe with a yellow plastic cap, marked with license number 21401 at the Meander Corner position using found monuments within the Southeast Quarter of Section 19 and the Southwest Quarter of Section 20. Four bearing tree ties were set as shown on the first page of this certificate. The set position of the Meander Corner is accepted as a perpetuation of the previous surveys listed above.

County Coordinates (Cass County North)

Northing = 207865.1094

Easting = 426206.8057