A000642624

OFFICE OF THE COUNTY RECORDER CASS COUNTY, MINNESOTA CERTIFIED, FILED, AND/OR RECORDED ON

7/25/2018 11:02:59 AM AS DOC #: A000642624 PAGES: 2 REC FEES: 0.00

KATHRYN M. NORBY CASS COUNTY RECORDER BY NG \_\_\_\_\_Dep TX#: 147795

Twp 141 Rge 26 Index No. E.0-21.0

		wp nge mdex no
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
Northeast corner of Section <u>11</u> ,Township <u>141 N.</u> ,Range <u>26 W., 5th</u> P.M.		
State of Minnesota, County of Cass		
•		
At the corner location shown on the sketch:		
On <sup>1</sup> 1 April 2018 found a 7/8 inch outside diameter iron pipe, capped RLS 42619,		
flush, 41 feet± east of centerline County Road #6.		
On	placed	
SKETCH OF REFERENCE TIES		
NOT TO SCALE Yard		
9	1.	
#	Open $\frac{x^{N}}{2}$	40d spike (2009) up 1.0 foot, E. side of 16 inch Red Pine
♣	·	of 16 inch Red Pine
Highway		1
l ∯ig	05071011 0	SECTION 1
	SECTION 2	40d spike (2009)
of	to c	40d spike (2009) up 1.0 foot in S. side of 12 inch Burr Oak
<u>ا</u> ه		of 12 inch Burr Odk
[ -		
nte		1.5
Centerline	Warren Lane	N 81 teet
		22.5' — — — —
<u> </u>	41'±	
		50.47 E Yard
I	OFOTION 44	51. 601
	SECTION 11	
		SECTION 12
I NOTE:	Open	A A M
All bearings are true	•	40d anika (2000)
County Coordinates		40d spike (2009) up 1.0 foot in S. side of 14 inch White Pine
(Cass County North) Northing 189656.91		Of 14 Inch white Fine
Easting 573130.80		
Statement of evidence relative to this corner location is on the back of this page.		
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licens <b>et</b> Land Surveyor under the laws		
of the State of Minnesota.		
1 mm VX		
		eeman, Cass County Surveyor
Date 7/25/18 MN License No. 21367		

A000642624

## Index No. E.0-21.0

## Statement of Evidence

## Northeast corner of Section 11, Township 141 North, Range 26 West, 5th Principal Meridian.

W.P. Allen and E.P. Putnam, General Land Office (GLO) Deputy Surveyors in the notes of the subdivision of Dec.

Township 141 North, Range 26 West, set a post for the original corner and referenced it as follows: 1871

31 links (20.46 feet) 8" Spruce S 73° E 10" Elm N 78° E

S 37° W 7" Tamarac N 34° W 40 links (26.40 feet) 8" Aspen 47 links (31.02 feet)

Said records are on file with the Minnesota Historical Society, St. Paul, Minnesota, copies are filed with the Cass County Highway Department, Surveyor's Office (CCHD/SO).

Soo Line Railroad map, on file with the United States Department of Agriculture, Forest Service offices in Cass Circa

1910 Lake, MN, indicate a distance of 2750' from the subject corner easterly to the south quarter corner of Section 1.

J.M. Greene, Surveyor, plat of WESTERN ADD. TO REMER, recorded on January 12, 1914 in the Cass County Nov. 1913 Recorders Office (CCRO) as Instrument Number 35766. The west line of said plat is dependent on the subject corner.

J.M. Greene, Surveyor, Plat of ELTRICH ADD. TO REMER, recorded on October 16, 1915 in the CCRO as Oct.

1915 Instrument Number 42200. This plat in the Northeast Quarter of the Northwest Quarter of Section 12 is dependent on the subject corner.

H. Colwell, assistant under G. Ralph, Engineer, survey of State Rural Highway #83, Survey Record #255, Book B, Circa

pages 86 & 87 and Curo Book 82, page 50 on file in the CCHD/SO, lists "Sec. Cor. 1, 2, 11, 12. 1915

F.F. Wilson, assistant engineer, County Ditch No. 8, Curo Field Book 191, on file at the CCHD/SO, page 3 states Aug. "We consult John Green Re: corners.... Page 16 states "SE cor. of sec. ....2637.5 I.M. ¼ between 1 & 2". 1916

Minnesota Department of Transportation(MN/DOT), Trunk Highway Number 6 right-of-way/alignment map labels Circa

1932 the subject corner as "at Int of Rds N, S. & E", and shows the location to be east of the proposed new centerline.

MN/DOT, Trunk Highway Number 6 right-of-way/alignment map 30-9, on file on the MN/DOT web site as Circa 1934 Document Number 1946364, shows the Highway centerline moving to the west approximately 40 feet.

D. Rieke. LS 5094, plat of MYERS, recorded on October 24, 1973 in the CCRO as Document Number 212388. Sept.

The subject corner is indicated as being set at a location 48.86 feet easterly of the centerline of Trunk Highway 1973 Number 6.

G. Stevenson, LS 12684, notes and worksheet of his subdivision of Section 1 on file at the Northern Engineering July

and Consulting Walker office indicates a 1-3/4 inch iron pipe in place at the subject corner and shows distances 1984 northerly and easterly to quarter corners.

R.A. Mustonen, LS 11946, Certificate of Survey in the NE 1/4 of the SE 1/4 Section 2, on file in the CCHD/SO, June

1997 indicates monuments set north and south of the south sixteenth corner between sections 1 and 2.

Oct. B. Hippen and C. Loe, technicians, records of the CCHD/SO, found a 1 inch pin, 3.3 feet west of centerline of

1998 State Highway #6, on centerline of Warren Lane.

M. Stefan, LS 12261, Certificate of Survey in the NW 1/4 of the SW 1/4 of Section 1, on file in the CCHD/SO, May

2000 indicates a bearing which is dependent on the subject corner.

M. Stefan, LS 12261, Certificate of Location, recorded on February 12, 2005 in the CCRO as Document Number May

A000496583 states "Corner is obliterated – no monument located....placed a 1½" x 24" Iron pipe driven flush with 2002 the surface of blacktop driveway".

Kramer Leas DeLeo(KLD), Certificate of Survey in the NE ¼ of the SE ¼ Section 2, on file in the CCHD/SO, May

2006 indicates the subject corner as recovered.

2006-J. Leas, LS 42619, met with Milo Stephan to discuss this corner. Mr. Stephan discovered a computational error 2009 with his position and agreed that the correct location should be 4 feet west. KLD field crews recovered all existing monuments in the Plat of ELTRICH ADD. TO REMER, and agreed with Mr. Stephan's corrected position. This position is also 2664.9 feet East of the North Quarter corner of Section 11, which matches the County Ditch Survey Distance.

J. Leas, LS 42619, in an unrecorded Certificate of Location of Government Corner, copy on file in the CCHD/SO, Dec. Set a ½ inch iron pipe for this corner, 40.8 feet east of centerline of Trunk Highway #6 and 4.38 feet west of 1.5 2009

inch pipe and witnessed as follows:

16" N. Pine

North

67.07 feet

12" Burr Oak

N 81° E

22.57 feet

14" W. Pine

S 51° E

50.41 feet

B. Hippen, technician, records of the CCHD/SO, found 7/8 inch outside diameter iron pipe, capped RLS 42619, May 2018 flush, in Warren Lane, all 2009 witnesses are in good condition.

The monument, recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument recovered by the CCHD/SO in 2018 is the accepted location of this corner.