


Index No. R 3

CASS COUNTY LAND CORNER RECORD

T. 133 R. 29 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 30 Corner common to sections 19 AND 30



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1870  
 Original monument lost

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species Bl. Pine Bl. Pine  
 Diameter 4" 3"  
 Bearing N54E S42W  
 Distance 31 LKS 77 LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1962 By MP&L  
 Location filed 1962 SUBA. GULL RIVER FLOWAGE, SEC. 19  
 Monument 1" REBAR & 2 BTS

Evidence of Subsequent Corner Restoration  
 Year of search 1977 By D. ANDERSON  
SUBDIVISION OF SEC. 19. REESTABLISHED  
PER MP&L 1962 INFO. HE NOTES THE FOLLOWING:  
1" I.P. VERIFIED

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

<u>N. PINE</u>	<u>POWER POLE</u>	<u>J. PINE</u>	<u>J. PINE</u>
<u>10"</u>	<u>?</u>	<u>12"</u>	<u>12"</u>
<u>STOE</u>	<u>N20W</u>	<u>S10E</u>	<u>SW</u>
<u>86.65</u>	<u>113.78</u>	<u>54.00</u>	<u>53.7'</u>
<u>(NEW P.P. PLACED)</u>		<u>OLD TIE</u>	<u>OLD TIE</u>

R-3

Subsequent Corner Restoration  
 Year surveyed 1999 By CCSO  
 Location filed CCSO Job. #98027  
 Monument Fd 13/8" OD IP, up 0.1', 47' S of  
& #36 & 39' W. of & Sylvan Hydroelec.  
Rd.  
11" R. Oak, N8°E, 173.29', dbl hd nail  
12" R. Pine, S54°E, 94.83', dbl hd nail  
11" R. Pine, S10°W, 64.12' " " "  
SE Wing Wall, N82°W, 321.76, 60d spike

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_