


T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 22 Corner common to sections 22 AND 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>W. BIRCH</u>	<u>W. BIRCH</u>	
Diameter <u>15"</u>	<u>8"</u>	
Bearing <u>NTSE</u>	<u>NB4W</u>	
Distance <u>4 LKS</u>	<u>36 LKS.</u>	

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1921 By E.B. Horst

Location filed COUNTY BOOK D P. 9

Monument SET 114 X 24" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1985 By DAVE LANDECKER

CORNER CERTIFICATE - DOC # 285674

Find 1" iron - set 2" sq iron w/ aluminum cap

Survey marker sign 3' South

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Bearing	Trees	Reference Objects
<u>Br. oak</u>	<u>N. Pine</u>	<u>N. Pine</u>
<u>6"</u>	<u>18"</u>	<u>4"</u>
<u>S64W</u>	<u>NT7E</u>	<u>S87E</u>
<u>62.23'</u>	<u>53.89'</u>	<u>67.19'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

PLAT - WHEEL LOCK SHORES

MYRON LANDECKER 1980

Certificate - Dave Landecker - 1985

Doc. # 285674