


T. 134 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 11 Corner common to sections 2, 11



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1868  
 Original monument POST

Bearing	Species	Trees
<u>N13E</u>	<u>W. PINE</u>	<u>N. PINE</u>
<u>37 LKS</u>	<u>9"</u>	<u>18"</u>
<u>N76 1/2 W</u>		
<u>90 LKS.</u>		

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**  
 Year of search 1993 7/26 By Lowell Pommerening  
 Placed a 1 1/4 x 5/4" iron pipe, up 18" above water surface.  
 10-18-93 Cert. Filed by: Lowell Pommerening,  
 RLS #17005, Doc. # 351994

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>White Oak</u>	<u>32"</u>	<u>N16E</u>	<u>38.33</u>
<u>White Oak</u>	<u>10"</u>	<u>N44W</u>	<u>31.17</u>
<u>White Oak</u>	<u>8"</u>	<u>N75W</u>	<u>21.08</u>
<u>Pine Stump</u>	<u>22"</u>	<u>N84W</u>	<u>59.40</u>

**Subsequent Corner Restoration**  
 Year surveyed 1998 By Landecker 1700B  
 Location filed CCSO  
 Monument Certificate of survey indicates monument found.

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_