


T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 29 Corner common to sections 20, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1868

Original monument Post

Species	Bearing	Trees
<u>N. PINE</u>	<u>N. PINE</u>	
<u>28"</u>	<u>28"</u>	
<u>N30E</u>	<u>S8W</u>	
<u>20 LKS</u>	<u>33 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1963 By Co Hwy Dept

Location filed Co RD # 34

Monument 1. P. in place 653' E of P. 1. 34; 1

1950 - Co Hwy Dept - (GRV#1) 1.P. 655' E. of P. 1

Evidence of Subsequent Corner Restoration

Year of search 1987 By Dave Landecker

Corner Certificate - Doc # 302264

Find 2 1/2" 1.P. w/ 3" cap

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Jack Pine</u>	<u>4"</u>	<u>N31E</u>	<u>35.49'</u>
<u>Burr oak</u>	<u>5"</u>	<u>S82E</u>	<u>21.62'</u>
<u>Burr oak</u>	<u>3"</u>	<u>N79W</u>	<u>40.58'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Dave Landecker - 1987

Doc. # 302264

Feb 2005 D. Landecker #17008

Cert. of Surv. shows mon. found

Apr. 2003 D. Landecker #17008

Cert. of Surv. shows Mon. Found

Aug 2002 J. Kramer #23668

Cert. of Surv. shows Mon. Found

March 2004 J. Kramer #23668

Cert. of Surv. shows mon. found