


T. 134 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 30 Corner common to sections 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1868  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	<u>BL. PINE</u>	<u>N. PINE</u>	_____
Diameter	<u>13"</u>	<u>18"</u>	_____
Bearing	<u>NBW</u>	<u>N75E</u>	_____
Distance	<u>6 LKS.</u>	<u>4 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed June 2003 By P. Trottier - 41002  
Location filed \_\_\_\_\_  
Monument Cert. of Surv. shows Mon. found

Evidence of Subsequent Corner Restoration

Year of search 2-10-03 By P. Trottier # 41002  
CCRO # A000483080  
1/2" iron pipe w/ plastic cap stamped RLS # 1008

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>OAK</u>	<u>OAK</u>	<u>OAK</u>	<u>OAK</u>
<u>10"</u>	<u>12"</u>	<u>8"</u>	<u>18"</u>
<u>N 44° W</u>	<u>S 24° W</u>	<u>S 70° E</u>	<u>N 4° E</u>
<u>8.28'</u>	<u>36.53'</u>	<u>18.69'</u>	<u>40.61'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_