


T. 134 R. 30 M. 5th Coordinates: X _____ Y _____

E/4 36 Corner common to sections 36 and 31-134-29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Bl. Oak</u>	<u>Aspen</u>
Diameter	<u>9"</u>	<u>3"</u>
Bearing	<u>S 65° W</u>	<u>N 25° E</u>
Distance	<u>10 lks.</u>	<u>27 lks.</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 3-24-04 By D. Landecker #17008
Location filed CCRO # A000488143
Monument Set 1" iron pipe with plastic cap #17008

? See Cert.
V

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>MAPLE</u>	<u>MAPLE</u>
Diameter	<u>12"</u>	<u>12"</u>	<u>10"</u>
Bearing	<u>N 19° W</u>	<u>N 77° W</u>	<u>S 10° W</u>
Distance	<u>23.45'</u>	<u>24.09'</u>	<u>6.32'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

