


Index No. C 5

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
E 14 S 6 Corner common to sections 5, 6



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1869
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Aspen Aspen
Diameter 10" 4"
Bearing N75E S54W
Distance 12 LKS. 5 LKS.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1993 Oct By Thomas Thiessen
Placed 1/2" iron pipe, monument capped RLS
#16097.
4-26-94 Cert. Filed by Thomas Thiessen, RLS
#16097, Doc. #35710P.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>Red Oak</u>	<u>White Oak</u>	<u>Red Oak</u>	<u>Red Oak</u>
<u>20"</u>	<u>14"</u>	<u>15"</u>	<u>20"</u>
<u>N40°E</u>	<u>N38°W</u>	<u>S40°W</u>	<u>S85°E</u>
<u>54.35</u>	<u>31.24</u>	<u>35.25</u>	<u>47.47</u>

C-5

Subsequent Corner Restoration

Year surveyed 5/2001 By CCSO
Location filed f.1e #2000,045
Monument Found 1993 IP, 32'± E. of fence
line. Took bearings to existing
witnesses.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

July 1902, Trip rd order shows no survey

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____