


T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1869  
Original monument POST

Species	Bearing	Trees	
<u>SPRUCE</u>	<u>SPRUCE</u>	<u>ASPEN</u>	<u>TAM</u>
Diameter <u>6"</u>	<u>18"</u>	<u>10"</u>	<u>4"</u>
Bearing <u>N77W</u>	<u>N60E</u>	<u>S31E</u>	<u>S34W</u>
Distance <u>12 LKS.</u>	<u>24 LKS.</u>	<u>47 LKS.</u>	<u>37 LKS.</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1915 By N. D. GORMAN  
Location filed COUNTY BOOK "B" P 484-495.  
Monument SET CORNER PROPORTIONALLY POSSIBLE I.M.

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Evidence of Subsequent Corner Restoration**

Year of search 1985 By FREEMAN  
Testimony of Jim Ackerson says I.P. was bladed out.  
Searched area of P.I. roads - no iron SET CI MON IN

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
<u>CFP</u>	<u>TELE. POLE</u>	<u>3" x 36" TELESPAR REF.</u>
<u>S57E</u>	<u>N32E</u>	<u>S45W</u>
<u>36.45</u>		<u>50.20</u>

**Subsequent Corner Restoration**

Year surveyed 3/2001 By CCSO  
Location filed CCSO  
Monument Found CIM, down 0.3', 3' E of E CR #102 and 3' N. of E 116th St. Also found 1985 Telspar & CFP witnesses, added the following.

<u>P. Pole</u>	<u>S50°E</u>	<u>43.00 *</u>
<u>PK N. end CMP</u>	<u>N70°E</u>	<u>22.65 *</u>

\* distance to double head nail

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
3-19-90 Cert. Filed by Walter Curo, RLS 11395 Doc. #819105.  
June 1902, Twp rd order shows no survey