


Index No. E 9

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 8 Corner common to sections 4, 5, 8, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>6"</u>	<u>7"</u>
Bearing	<u>N 17 W</u>	<u>N 39 E</u>	<u>S 42 W</u>	
Distance	<u>56 LKS</u>	<u>N 88 LKS</u>	<u>77 LKS.</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 3-14-92 By Thomas Thiessen

Location filed Cert. Filed Doc. # 343236

Monument Set 1/2" iron pipe monument capped
RLS No 16097 at E - E

Bearing Trees, Reference Objects

Species	<u>POWER POLE</u>	<u>TWIN OAK</u>	
Diameter	<u>10"</u>		
Bearing	<u>NE</u>	<u>SE</u>	<u>SW</u>
Distance	<u>39.24'</u>	<u>80.85'</u>	<u>65.85'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

11-24-92 Cert. Filed by Thomas Thiessen
RLS No. 16097 Doc. # 343236

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____