


Index No. C 13

CASS COUNTY LAND CORNER RECORD

T. 135 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 4 Corner common to sections 3, 4



EXISTING SURVEYS

Original Government Survey
Year surveyed 1865
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species BL. PINE BL. PINE
Diameter 4" 9"
Bearing S87 1/2 E S58 1/2 W
Distance 47 LKS 71 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1917 By Curo
Location filed micraf. in - roll 1105 BK 56 P. 123
Monument Set 3X3X24" Br. oak post proportionally

Evidence of Subsequent Corner Restoration
Year of search 1978 By Landecker
iron imple RLS # 3091
6" oak NW 35.18', 5" oak SW 21.70',
6" oak NE 23.60'
1/10/84 - Freeman - Marcum - Fnd 1 1/2" IP. Flush
w/ RLS # 3091 - also 1974 + 1978 trees: - put
disc on side of tree

Bearing Trees, Reference Objects
Species J. Pine J. Pine
Diameter 10" 10"
Bearing S 28-05 W N 71 E
Distance 42.10' 32.43'
scribed 22 yrs ago


Bearing Trees, Reference Objects
Species R. oak R. oak R. oak
Diameter 6" 5" 6"
Bearing N 60° E S 8° W N 4° W
Distance 24.00' 21.93' 18.63'

Subsequent Corner Restoration
Year surveyed 1984 By Freeman - Marcum
Location filed _____
Monument Fnd 1 1/2" IP. v. p. 3' set by Dean Anderson
m 1952
Br. oak 4" N 22° W 16.30'
Br. oak 4" N 60° E 10.08'

Evidence of Subsequent Corner Restoration Found
Year of search 1999 By Landecker & Assoc.
Cert. of Survey indicates
monument found.
March 1923
Twp Road order shows no survey

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____

T. 135 R. 29 M. 5TH Coordinates: X _____ Y _____
QUARTER Corner common to sections 3 - 4



EXISTING SURVEYS

Original Government Survey
Year surveyed 1865
Original monument POST

Original Evidence Found D.M.
Year of search 1952 By ANDERSON
Monument found IRON PIPE IN PLACE
PAGE 40, BOOK 69
1972: PAGE 69, BOOK 232: IN PLACE: 1976 = Corner Book 232

Bearing Trees
Species BLK PINE BLK PINE
Diameter 1 1/2" 9"
Bearing S 81 1/2° E S 58 1/2° W
Distance 47 IK 71 IK

Original Bearing Trees Found
Species OAK OAK OAK
Diameter 7" 10" 6"
Bearing N 1/2° W N 1/2° E S 5° W
Distance 18.35' 23.58' 21.75'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

