


T. 135 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 19 Corner common to sections 19, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Aspen
Diameter 16"
Bearing N 2 3/4 W
Distance 850 LKS.

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1978 By CO HWY DEPT
Location filed Co RD # 77
Monument 2" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1904 By W. Hallett
Twp. Road Order, Surveyors Report note
witnesses.

(Book B, pg 129, J. Caro states this
is probably no good)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

N. Pine N. Pine
7" 6"
N 74° E N 86 3/4° W
30 LKS 38 1/2 LKS
(19.8') (25.4')

P-5

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument P. Sandwich Apr 2001
Cert. of Surv shows Mon. found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Oct. 1903 W. H. Hallett
Twp rd order shows survey

7/2003 - CCSO #2001.024 found Alum.
Cap tel spar, 4 1/2 W. of E Co. Rd.
#107.
10" J. Pine 585°E 61.76' *
9" J. Pine 544°W 101.76' *
P. Pole N45°W 37.89' *
*distance to double head nail

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____