


T. 135 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 31 Corner common to sections 29, 30, 31, 32



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1865  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing Trees			
	TAM	TAM	TAM	TAM
Diameter	7"	5"	9"	6"
Bearing	N55E	N47W	S60W	S52E
Distance	12 LKS	11 LKS	21 LKS	27 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration  
 Year surveyed 1916 By E. B. HORST  
 Location filed COUNTY BOOK 'B' P. 538-541  
 Monument FND OLD GOUT STAKE + ALL BITS DEAD.  
SET 2x4x8" BOILER FIVE  
1916, E.B. HORST BOOK 'B' P. 550-553 FND I.M.  
also on microfilm - roll 105 BK 64 P. 43, 45

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
← also on microfilm - roll 105 BK 66 P. 119, 144  
1985 - Dave Landecker - Corner Certificate - Doc # 285845  
Fnd 2" Boiler Five up 16"  
Survey marker sign next to Monument

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance	Reference Objects
Bl. Spruce	6"	S25E	26.45'	part of highway (Norway pines)
Tam	6"	South	27.56'	East
Tam	6"	N66W	3.88'	± 75'
Bl. Spruce	4"	N75E	9.52'	

V-5

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Landecker - 1985  
Doc. # 285845